

1793 North Applebury Place, Fayetteville, Arkansas 72701

Inspection Date:

05/05/2011

Prepared For:

Brandon and Amanda Nichols

Prepared By:

Kelso Home Inspections 2472 N. Robin Road Fayetteville, Arkansas 72703

(479) 236-6544
Fax: (479) 251-7566
pakelso@gmail.com
www.kelsohomeinspections.com

Report Number:

050611A

Inspector:

Paul Kelso

© 2011 Kelso Home Inspections

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 2 of 47

TABLE OF CONTENTS

REPORT	3
RECEIPT/INVOICE	4
GROUNDS	5
ROOF	6
EXTERIOR	7
ELECTRICAL/AC	8
KITCHEN/LAUNDRY	9
BATHROOMS	10
ROOMS	12
ROOMS	14
INTERIOR	15
PLUMBING	16
HEATING	17
ELECTRIC/COOLING	18
SUMMARY	19

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 3 of 47

REPORT OVERVIEW

THE HOUSE IN PERSPECTIVE

CONVENTIONS USED IN THIS REPORT

SATISFACTORY - Indicates the component is functionally consistent with its original purpose but may show signs of normal wear and tear and deterioration.

MARGINAL - Indicates the component will probably require repair or replacement anytime within five years.

POOR - Indicates the component will need repair or replacement now or in the very near future.

MAJOR CONCERNS - A system or component that is considered significantly deficient or is unsafe.

SAFETY HAZARD - Denotes a condition that is unsafe and in need of prompt attention.

THE SCOPE OF THE INSPECTION

All components designated for inspection in the ASHI® Standards of Practice are inspected, except as may be noted in the "Limitations of Inspection" sections within this report.

It is the goal of the inspection to put a home buyer in a better position to make a buying decision. Not all improvements will be identified during this inspection. Unexpected repairs should still be anticipated. The inspection should not be considered a guarantee or warranty of any kind.

Please refer to the pre-inspection contract for a full explanation of the scope of the inspection.

BUILDING DATA

Approximate Age: 47+ Years
Style: Single Family

Main Entrance Faces: For the sake of the report the house faced the east.

State of Occupancy: Occupied
Weather Conditions: Sunny
Recent Rain: Yes

Ground cover: Dry with a temperature of ove 65°F

RECEIPT

Kelso Home Inspections 2472 N. Robin Road Fayetteville, Arkansas 72703 (479) 236-6544

Date: 05/05/2011 Inspection Number: 050611A

Name: Brandon and Amanda Nichols

Inspection: \$310

Other**

Total: \$310

☑ Check #: 8294

☐ Cash

Inspected By: Paul Kelso License/Certification #: AR HI 1417

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 5 of 47

GROUNDS							
SERVICE WAI	KS None	☐ Public sidewal	lk needs repair				
Material:	✓ Concrete	✓ Flagstone	☐ Gravel	☐ Brick	☐ Other		
Condition:	☑ Satisfactory to	✓ Marginal	□ Poor	☑ Trip Hazards			
	☐ Pitched toward:	s home	tling cracks	☐ Not visible	☐ Typical cracks		
DRIVEWAY/PA	ARKING D No	one					
Material:		☐ Asphalt	☐ Gravel/Dirt	☐ Brick	☐ Other		
Condition:	☐ Satisfactory	✓ Marginal	Poor	☐ Fill cracks and sea			
	☐ Pitched toward:	s home	☐ Trip hazard	☑ Settling Cracks	☐ Typical crack		
PORCH (covere			—				
Support Pier:	☐ Concrete	□ Wood	✓ Not visible	Other			
Condition:	✓ Satisfactory to	•	□ Poor	☐ Railing/Balusters	recommended		
Floor:	☑ Satisfactory to	✓ Marginal	☐ Poor	☐ Safety Hazard			
STOOPS/STEPS	S □ None	☐ Uneven risers					
Material:	☐ Concrete	□ Wood	✓ Other	☐ Railing/Balusters			
Condition:	✓ Satisfactory	☐ Marginal	Poor	\square Cracked	☐ Settled		
	☐ Rotted/Damage	a	☐ Safety Hazard				
	None		☐ Kool-Deck®	□ p:.1-	□ T-: 1		
Material: Condition:	☐ Concrete☐ Satisfactory	☐ Flagstone ☐ Marginal	□ Poor	☐ Brick ☐ Settling Cracks	☐ Trip hazard		
Conditions	•	s home (See remar		☐ Drainage provided	☐ Typical cracks		
DECK/BALCO	NY (flat, floored, ro	oofless area) 🔲 🗅	None				
Material:	☑ Wood ☐ M		ite Not visible	☑ Railing/Balusters	recommended		
Finish:	☑ Treated (some r	*	_	✓ Painted/Stained	✓ Needs sealing		
Candition	☐ Improper attaci		☐ <i>Railing loose</i> ☐ Poor	☑ Wood in contact v			
Condition:	✓ Satisfactory				vun sou		
Negative Grade	G AFFECTING FO : ☑ East ☐ Wes		See remarks page) South	☐ Satisfactory			
-	d additional backfill		nd window wells/co	•	a back trees/shrubberies		
	ntact with/improper			served - not tested			
RETAINING V	WALL None	Material: Stone (f	ront) and concrete (so	outh end slab)			
Condition:	✓ Satisfactory	✓ Marginal	Poor	☐ Safety Hazard	\square Leaning/cracked/bowed		
(Relates to the visual c		_					
HOSE BIBS	□ None	✓ No anti-siphon		□ Not on			
Operates:	✓ Yes	□ No	☐ Not tested	□ Not on			
GENERAL CO	MMENTS						

Uneven slabs in walks, could be a tripping hazard, repair and/or replace as needed. Driveway had some settlement, but usable, repair as needed. Maintain a positive drainage slope away from the foundation. Trees need to be trimmed away from the house. The property had several retaining walls. The front rock retaining walls appeared to be in satisfactory condition. The cinder block retaining walls (south end exterior slab and wall beneath west portion of the deck) appeared to be in marginal condition, repair as necessary. The wood deck appeared to have some wood rot in a few areas and may need additional support if the wall beneath it fails, recommend a licensed general contractor further review and make any necessary repairs.

Any set of more-than-two steps is considered a potential safety hazard if no handrail is available. The parameter seating had no backs and should be a potential safety hazard as a fall can be farther than 6 feet.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 6 of 47

	SZ	RO	OF
☑ All	☐ Partial	□ None	☐ Limited by:
☑ Roof	☐ Ladder at eav	res Ground	(Inspection Limited)
	- Ladder at ear		(Inspection Linuxu)

INSPECTED F	ROM Z Roof	☐ Ladder at ea	ves	nd (Inspection Limite	ed) 🗆 With Binocu	ılars
STYLE OF RO Type: Pitch:	OF ☑ Gable ☑ Low	□ Hip □ Medium	☐ Mansard ☐ Steep	☐ Shed ☐ Flat	☐ Flat	☐ Other
ROOF COVER Roof: VENTILATIO Appears Adequ (See Interior ren	Type: Asphalt Es	e: ☐ Soffit ☐ No	+ Layers App ☐ Ridge ☐ Turbine	roximate age of co ✓ Gable ☐ Powered	over: 1-5 years an Roof Other	d 10+ years
FLASHING Condition:	Material: ☐ Not visible ☐ Separated from	☐ Galv/Alum☐ Satisfactory chimney/roof	☐ Asphalt ☐ Copper ☑ Marginal ☐ Recomment	☐ Not visible ☐ Foam ☐ Poor d Sealing	☐ Rubber ☐ Other ☑ Rusting ☐ Other	□ Lead
VALLEYS	□ N/A	Material:	☐ Galv/Alum		☐ Lead	☐ Copper
Condition:	✓ Not visible ☐ <i>Rusted</i>	☐ Satisfactory ☐ Holes	✓ Not visible ☐ Marginal ☐ Recommen	□ Poor		
CONDITION Condition:	□ Curling □ Nail popping ☑ Moss buildup	Roof: Cracking Granules missing Exposed felt	☐ Ponding		Broken/L	or oose Tiles/Shingles Tabs/Shingles/Tiles
SKYLIGHTS Condition:	☐ N/A ☑ Satisfactory to	☐ Cracked/Brok	ken □ Not □ Poor	visible		
PLUMBING V.		□ No □ Not Vi	☑ Satisfactory sible	y	□ Poor	

Conditions reported above reflect <u>visible</u> portion only

GENERAL COMMENTS

ROOF VISIBILITY

The roof appeared to have two different ages of shingles on it, the north end appeared to be 10+ years old while the south end appeared to be newer and between 1-5 years. The front eave roofline had some sagging and the gutter dipped in the same place, but the backside of the roof plane could not be inspected for any underside issues as this area had no attic space. Recommend contacting a general contractor if any moisture penetration becomes a result of any roofing issues. Many mirror sections of the interior skylights were cracked/broken, replace as necessary.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 7 of 47

EXTERIOR

CHIMNEY(S)	None	Location(s): Middle					
Viewed From:	Roof	☐ Ladder at eaves		vith binoculars		_	
Rain Cap/Spar		✓ Yes	□ No		ecommende		
Chase:	☐ Brick	✓ Stone	☐ Metal	□ B1		☐ Frame	
Evidence of:	☐ Holes in metal	Cracked chimney ca		rtar joints 🔲 Fl	aking \square	Loose Brick	☐ Rust
Flue:	☑ Tile	☐ Metal	\square Unlined		ot visible		
Evidence of:	☐ Scaling	☐ Cracks	Creosote			See remarks	page)
	☑ Have flue(s) clea	ned and re-evaluated	☐ Recomme	nd Cricket/Sadd	lle/Flashing		
Condition:	☑ Satisfactory to	✓ Marginal	□ Poor				
	UPPERS/EAVEST		✓ Needs to			□ Downspou	ts needed
Material:	☑ Galvanized/Alu	2		Copper		☐ Other	
Condition:	✓ Satisfactory	✓ Marginal	□ Poor		usting		
Leaking:	☐ Corners	☐ Joints	☐ Hole in n				
Attachment:	Loose	\square Missing spikes		rly sloped_(Se	_	page)	
Extension needed	l: □ North	☐ South	☐ East	\square W	est		
SIDING Material:	☐ Metal/Vinyl ☐ ☐ Typical cracks	Stone Wwood I Monitor	□ Block/Brick		board	See remarks p ☐ Fiber-ceme ☐ Loose/Miss	ent
Condition:	☑ Satisfactory to	✓ Marginal	☐ Poor	☑ Reco	mmend pair	ting	
TRIM, SOFFI	Γ, FASCIA, FLASH	ING					
Material:	☑ Wood	☐ Fiberboard	☐ Aluminur	m/Steel	☐ Fiber C	ement [☐ Stucco
	✓ Recommend rep	air/painting	☐ Damaged	l wood	☐ Other		
Condition:	☑ Satisfactory to	-	□ Poor				
CAULKING		C					
Condition:	☐ Satisfactory	✓ Marginal	□ Poor				
Condition.		und windows/doors/ma		orners/utility n	onotrations		
				orners/utuuy p	enenunons		
WINDOWS &		\square Failed/fogged ins					
Material:	□ Wood	☐ Metal	✓ Vinyl		luminum/Vi	•	
Condition:	Satisfactory	☐ Marginal	☐ Poor	☐ Wood rot	□ Recom	mend repair/p	painting
STORMS WIN	DOWS None	☐ Not installed	□ Wood	☐ Metal	□ Wood/ı	netal comb.	
Putty:	☐ Satisfactory	☐ Glazing/caulk ne		□ N/A			
Condition:	☐ Satisfactory	☐ Broken/cracked	☐ Wood rot		□ Recom	mend repair/p	ainting
	•				_ 11000,,,,	nena repair, p	8
	ADE/FOUNDATIO	· ·		l Space)			
Stem Wall:	☑ Concrete block		Other		_		
Condition:	✓ Satisfactory	✓ Marginal	Poor		☐ Not vis	ible	
Slab:	Post tensioned	✓ Poured concrete	Other				
Condition:	☐ Satisfactory	☐ Marginal	☐ Poor	(See comment	ts page)	☑ Not visible	
GENERAL CO	OMMENTS						

Flashing areas around the chimney chase appeared to be in marginal condition and allowing moisture to penetrate into the attic and on the ceiling in front of the chimney chase, recommend a licensed general contractor further review and make any necessary repairs. Gutters had some incorrectly pitched areas, with standing water, and were in need of correction. Siding and trim appeared to be all intact and in overall good condition, recommend painting and exposed wood for protection. Siding was in contact with soil, recommend creating as much clearance as possible of the siding from the soil. Recommend home have an active termite policy. Correct any low areas that could hold water next to the foundation and fill any gaps in the foundation where water could enter/intrude.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 8 of 47



□ Underground Exterior outlets: GFCI present: ☑ Reverse polar	✓ Overhead ✓ Yes ✓ Yes	No O	perative: [perative: [mast needs repair ✓ Yes □ No ✓ Yes ☑ No ✓ Safety Hazard	Condition: ☐ Sat. ☑ M ☑ Overhead w ☐ Less than 3' from balcon	
Front entry light	did not appear	to operate	at the time o	of the inspection.		
the deck – potentin the front, elect	tial safety haza trical wires sho	ards. Electould be eith	rical wires we ner run withir	ere visible and run al	al wires were only about 5 fe ong outside the house and out e conduit. The electrical mass are penetration.	t the front hose bibb
BUILDING(S) Type: Condition:	EXTERIOR V ✓ Not visible ☐ Satisfactor	e 🗆 1	ONSTRUCTI Framed Marginal	ION ☐ Masonry ☐ Poor	☐ Other ☑ Not visible	
EXTERIOR DO		rance (1);	To carport ((2); To deck from li	ing room (3); To deck from	master bedroom
Weatherstripping Door Condition:			Iarginal Marginal	□ Poor 4 Poor	1 Missing bottom strip	
Recommend rep	lacing the botto	om weathe	r strip of the	front entry door.		
EXTERIOR A/ UNIT #1: Brand: Unknow Outside Disconnect Level: Condenser Fins: Condition:	□ N/A n : ☑ Yes □ ☑ Yes □	Loo Mo I No Ma I No 🗆 (cation: West del #: 867.8 ximum fuse/b Cabinet/hous Need cleaning Marginal	16850 breaker rating: 45 A sing rusted	Approximate age: Older that np Fuses/breakers Improperly sized fuses/br Damaged base/pad	installed: Unknown
UNIT #2: Brand: Goodman Outside Disconnect Level: Condenser Fins: Condition:	Yes □ Yes □	Mo No Ma No D	cation: West del #: GSH1 ximum fuse/b Cabinet/hous Need cleaning Marginal	30241BA breaker rating: 20 Ar sing rusted	Approximate age: 1-5 yrs The property sized fuses/broad Damaged base/pad	s installed: Unknown reakers

GENERAL COMMENTS

The ages of both A/Cs/heat pump were not confirmed yet the one appeared to be an older unit while the newer heat pump appeared to be 1-5 years old. Outside compressor unit coils could be cleaned to improve efficiency.

The wire around the disconnect to the older A/C unit was wearing thin while it was wrapped around a corner, recommend repairing before the insulation is worn so thin that the box would be energized and a safety hazard.

1793 North Applebury Place, Favetteville, Arkansas 72701 Page 9 of 47 KITCHEN COUNTERTOPS **✓** Satisfactory ☐ Marginal ☐ Recommend repair/caulking **CABINETS** ✓ Satisfactory to ✓ Marginal **☑** May need adjustments PLUMBING COMMENTS ☐ Yes ✓ No ✓ No **Faucet Leaks: Pipes leak/corroded:** □ Yes ✓ Satisfactory ☐ Corroded ☐ Chipped ☐ Recommend repair Sink/Faucet: ☐ Cracked **Functional Flow: Functional Drainage:** ✓ Adequate □ Poor ✓ Adequate ☐ Poor WALLS & CEILING Condition: ✓ Satisfactory ☐ Marginal ☐ Poor ☐ Typical cracks ☐ *Moisture stains* HEATING / COOLING SOURCE □ No ✓ Yes FLOOR ☐ Poor **Condition:** ✓ Satisfactory ☐ Marginal ☐ Sloping ☐ Squeaks APPLIANCES (See remarks page) **☑** Disposal □ No ☐ Trash compactor ☐ Yes □ No Operates: □ No ✓ Oven Operates: ✓ Yes □ No ✓ Exhaust fan ✓ Yes Operates: Range *Operates*: **V** Yes \square No ☑ Refrigerator Operates: ✓ Yes \square No **✓** Dishwasher *Operates*: ✓ Yes □ No ✓ Microwave *Operates*: ✓ Yes □ No Anti-tip bracket installed behind oven/range: \square Yes ✓ N/A □ No Dishwasher Airgap: ☐ Yes ✓ No Dishwasher Drain Line Looped: ✓ Yes **Outlets Present:** ✓ Yes □ No Operable: ☐ Yes \square No **G.F.C.I.:** ☐ Yes ✓ No Operable: ☐ Yes □ No Open ground/Reverse polarity within 6' of water: ✓ Yes □ No **✓** Potential safety hazard(s) GENERAL COMMENTS There were no visible active piping leaks at the time of the inspection. Drain lines had no visible leaks or signs of backup at the time of inspection. Countertops and cabinets had normal wear. The back left burner of the stovetop did not fire, repair as necessary. The electrical outlets did not appear to be GFCI protected – potential safety hazard. Patchwork was noted on the ceiling. LAUNDRY ROOM ROOM COMPONEN Laundry sink: ✓ N/A Faucet leaks: \square Yes \square No Pipes leak: ☐ Yes ☐ No ☐ Yes **Room vented:** □ Yes ☑ No **Cross connections:** □ No ☐ Yes ☑ No Heat source present: **Dryer vented:** \square N/A □ Wall ✓ Ceiling ☐ Floor ☐ Not vented □ Not vented to Exterior ☐ Recommend repair ☐ Safety hazard Open ground/reverse polarity within 6' of water: ☐ Yes ☑ No ☐ Safety hazard **Electrical:** ☐ Yes ✓ No **Operates:** ☐ Yes ☐ No **G.F.C.I.** present: **✓** Washer **☑** Dryer ☐ Water heater ☐ Furnace **Appliances:** Washer hook-up lines/valves: ☐ Leaking ☐ Corroded ✓ Not visible Gas Shut-off Valve: □ N/A ☐ Yes □ No ☐ Cap Needed ☐ Safety hazard ✓ Not visible GENERAL COMMENTS

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 10 of 47



BATH: MASTER BATH				
SINKS / TUBS / SHOWERS Faucet leaks: ☐ Yes ☑ No Fixture(s) Condition:	Loose: ☐ Yes ☐ Satisfactory to	☑ No ☑ Marginal	Pipes leak: ☐ Poor	☐ Yes ☑ No
TOILET Bowl Loose: ☐ Yes ☑ No	Operates: Ves	□ No □ Toilet leak	ks	l/tank □ Cross connection
SHOWER / TUB AREA / SINK(Material: ☑ Ceramic/Plast Condition: ☑ Satisfactory Caulk/Grouting Needed: Functional Drainage:	ic □ Fiberg. ☑ Marginal □ Yes ☑ No ☑ Adequate	☐ Poor Where:	☐ Masonite ☐ Rotted floors Functional Flow:	☐ Other ✓ Adequate ☐ Poor
WALLS / CEILING / CABINET Moisture stains present: G.F.C.I. Present: Open ground/Reverse polarity w	☐ Yes ☑ No ☐ Yes ☑ No	Outlets present: Operates: ✓ Yes □ No Po	✓ Yes □ No □ Yes □ No otential safety hazards	s present: ☑ Yes ☐ No
HEATING / COOLING SOURCE Window/Door: ✓ Yes ✓ No (so Exhaust Fan: ☐ Yes ✓ No		☐ No ☑ Satisfactory ☐ Yes ☐ No	☐ Marginal Noisy: ☐ Yes	□ Poor □ No
GENERAL COMMENTS Sink drained slowly, recommend returned on the stop valve, let the toil repairing. BATH: EAST BATHROOM				
SINKS / TUBS / SHOWERS Faucet leaks: ☐ Yes ☑ No Fixture(s) Condition:	Loose: ☐ Yes ☐ Satisfactory to	☑ No ☑ Marginal	Pipes leak: ☐ Poor	☐ Yes ☑ No
TOILET Bowl Loose: ☐ Yes ☑ No	Operates: ✓ Yes	☐ No ☐ Toilet leak	ks	l/tank □ Cross connection
SHOWER / TUB AREA / SINK(Material:	ic	☐ Poor	☐ Masonite ☐ Rotted floors tub Functional Flow:	☐ Other ✓ Adequate ☐ Poor
WALLS / CEILING / CABINET Moisture stains present: G.F.C.I. present: Open ground/Reverse polarity w	☐ Yes ☑ No ☑ Yes ☐ No	Outlets present: Operates: ✓ Yes □ No Po	✓ Yes □ No ✓ Yes □ No otential safety hazards	s present: ☐ Yes ☑ No
HEAT / COOLING SOURCE Window/Door: ✓ Yes ☐ No Exhaust Fan: ✓ Yes ☐ No GENERAL COMMENTS Any window that is within or above ground most likely due an older set doors did not lock easily, repair as	rvice wire without a gr		ntial safety hazard.	

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 11 of 47

	_			
BATH: SOUTH BATHROOM				
SINKS / TUBS / SHOWERS				
Faucet leaks: ☐ Yes ☑ No	Loose: □ Yes	☑ No	Pipes leak:	☐ Yes ☑ No
Fixture(s) Condition:	✓ Satisfactory	☐ Marginal	Poor	
TOILET	·	C		
	Operates: ✓ Yes	□ No □ Toilet leal	s	l/tank
		ino in rolletteal	Cruckeu bow	gunk 🗀 Cross connection
_SHOWER / TUB AREA / SINK			_	_
Material: ✓ Ceramic/Plas	tic ☑ Fiberg	lass	☐ Masonite	☐ Other
Condition: ✓ Satisfactory	☐ Marginal	□ Poor	☐ Rotted floors	
Caulk/Grouting Needed:	☐ Yes ☑ No	Where:		
Functional Drainage:	✓ Adequate	□ Poor	Functional Flow:	✓ Adequate ☐ Poor
WALLS / CEILING / CABINET	TS T			•
Moisture stains present:	☐ Yes ☑ No	Outlets present:	✓ Yes □ No	
G.F.C.I. present:	✓ Yes □ No	Operates:	✓ Yes □ No	
Open ground/Reverse polarity w	vithin 6' of water:	☐ Yes ☑ No Po	otential safety hazards	s present: ☐ Yes ☑ No
HEAT / COOLING SOURCE	✓ Yes □ No			
Window/Door: ✓ Yes ✓ No	✓ Satisfactory	☐ Marginal	□ Poor	
Exhaust Fan: ✓ Yes □ No	Operates:	✓ Yes □ No	Noisy: □ Yes	☑ No
GENERAL COMMENTS				
	The pocket doors did r	not lock easily, repair	r as necessary.	

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 12 of 47



LOCATION: NORTH LIVING ROOM

Walls & Ceiling	g: 🗹 Satisfad	ctory to 🗹 M	larginal		☐ Poor		
	Moisture		✓ Yes		□ No	Where: NE and	SW corners had some
peeling sheet ro		indicating poss	_	to moistur			
Floor:		ctory to 🗹 M			Poor	☐ Squeaks	☑ Slopes
	Typical cı	racks:	✓ Yes		□ No		
Ceiling Fan:	□ N/A	_	✓ Satisfacto	•	-	_ Poo	
Electrical:	Switches:	✓ Yes	□No	Outlets:	✓ Yes	☐ No Operates:	
Heating/Cooli		nd/Reverse po ☐ Yes	larity: ☑ No	☐ Yes Holes:	✓ No □ □ Doors	l Coverplates missing ☐ Walls ☐ Ceil	•
Bedroom Egre			☐ Yes	□ No	□ Doors	□ wans □ Cen	iligs
Doors & Wind		Operational:	✓ Yes	□ No			
		Locks/Latches	Operable:	✓ Yes	□ No	☐ Missing ☐ Crae	cked Glass
GENERAL C	OMMENTS						
Fan lights did r			me of the insp	pection.			
LOCATION:			[7] M		□ n		
Walls & Ceiling	g: Moisture	•	✓ Marginal☐ Yes	Į.	□ Poor ☑ No	Where:	
Floor:		ctory to M			□ Poor	□ Squeaks	☐ Slopes
11001.	Typical ci	•	☐ Yes		☑ No	□ Squeaks	□ blopes
Ceiling Fan:	□ N/A		✓ Satisfactor	orv to		□ Poo	r
Electrical:	Switches:	✓ Yes	□ No	Outlets:	✓ Yes	☐ No Operates:	
		nd/Reverse po	larity:	☐ Yes	☑ No ☑	Coverplates missing	
TT 42 1/C 12	~	─					
Heating/Cooli		✓ Yes	□ No	Holes:	\square Doors	☐ Walls ☐ Ceil	ings
Bedroom Egre	ess Restricted	d: □ N/A	☐ Yes	✓ No		☐ Walls ☐ Ceil	ings
	ess Restricted	d: □ N/A Operational:	☐ Yes ☑ Yes (see	☑ No note)	□ No		
Bedroom Egro Doors & Wind	ess Restricted lows:	d: N/A Operational: Locks/Latches	☐ Yes ☑ Yes (see	✓ No	□ No	□ Walls □ Ceil	
Bedroom Egre Doors & Wind	ess Restricted lows:	d: □ N/A Operational: Locks/Latches	☐ Yes ☑ Yes (see Operable:	✓ No note) ✓ Yes (se	□ No ee note) □	l No □ Missing □	Cracked Glass
Bedroom Egre Doors & Wind	ess Restricted lows:	d: □ N/A Operational: Locks/Latches	☐ Yes ☑ Yes (see Operable:	✓ No note) ✓ Yes (se	□ No ee note) □		Cracked Glass
Bedroom Egre Doors & Wind GENERAL C The bedroom d	ess Restricted lows: OMMENTS loor did not lo	d: \Box N/A Operational: Locks/Latches ock well and the	☐ Yes ☐ Yes (see Operable:	☑ No note) ☑ Yes (so	□ No ee note) □ ot move well	l No □ Missing □	Cracked Glass
Bedroom Egre Doors & Wind GENERAL C	ess Restricted lows: OMMENTS loor did not lo CENTER L g: Satisfac	d: Operational: Locks/Latches ock well and the IVING ROOM ctory	☐ Yes ☑ Yes (see Operable: e sliding glass ☑ Marginal	☑ No note) ☑ Yes (so	□ No ee note) □ ot move well □ Poor	l No ☐ Missing ☐ , repair as necessary.	Cracked Glass
Bedroom Egre Doors & Wind GENERAL Co The bedroom d LOCATION: Walls & Ceiling	ess Restricted lows: OMMENTS loor did not lo CENTER L g: Satisfac Moisture	d: N/A Operational: Locks/Latches ock well and the IVING ROOM ctory stains:	☐ Yes ☑ Yes (see Operable: e sliding glass ☑ Marginal ☑ Yes	☑ No note) ☑ Yes (so	□ No ee note) □ ot move well	l No ☐ Missing ☐ , repair as necessary.	Cracked Glass
Bedroom Egre Doors & Wind GENERAL C The bedroom d LOCATION: Walls & Ceiling south ceiling an	OMMENTS loor did not lo CENTER L g: Satisfac Moisture rea around the	d: \Box N/A Operational: Locks/Latches ock well and the IVING ROOM ctory stains: e chimney chase	☐ Yes ☑ Yes (see Operable: e sliding glass ☑ Marginal ☑ Yes e.	☑ No note) ☑ Yes (so	□ No ee note) □ ot move well □ Poor □ No	l No ☐ Missing ☐ , repair as necessary. Where: Corner	Cracked Glass of east skylight and the
Bedroom Egre Doors & Wind GENERAL Co The bedroom d LOCATION: Walls & Ceiling	OMMENTS loor did not lo CENTER L g: Satisfac Moisture rea around the	Operational: Locks/Latches ock well and the IVING ROOM ctory stains: c chimney chase ctory to M	☐ Yes ☑ Yes (see Operable: e sliding glass ☑ Marginal ☑ Yes e. Iarginal	☑ No note) ☑ Yes (so	□ No ee note) □ ot move well □ Poor □ No □ Poor	l No ☐ Missing ☐ , repair as necessary.	Cracked Glass
Bedroom Egre Doors & Wind GENERAL C The bedroom d LOCATION: Walls & Ceiling south ceiling ar Floor:	OMMENTS loor did not lo CENTER L g: Satisfac Moisture rea around the	Operational: Locks/Latches ock well and the IVING ROOM ctory stains: c chimney chase ctory to M	☐ Yes ☑ Yes (see Operable: e sliding glass ☑ Marginal ☑ Yes e. larginal ☐ Yes	☑ No note) ☑ Yes (so	□ No ee note) □ ot move well □ Poor □ No □ Poor ☑ No	No ☐ Missing ☐ , repair as necessary. Where: Corner ☐ Squeaks	Cracked Glass To feast skylight and the □ Slopes
Bedroom Egre Doors & Wind GENERAL C The bedroom d LOCATION: Walls & Ceiling south ceiling an	OMMENTS loor did not lo CENTER L g: Satisfac Moisture rea around the Satisfac Typical ci	Operational: Locks/Latches ock well and the IVING ROOM ctory stains: c chimney chase ctory to M	☐ Yes ☑ Yes (see Operable: e sliding glass ☑ Marginal ☑ Yes e. Iarginal	☑ No note) ☑ Yes (so	□ No ee note) □ ot move well □ Poor □ No □ Poor	No ☐ Missing ☐ , repair as necessary. Where: Corner ☐ Squeaks	Cracked Glass of east skylight and the Slopes
Bedroom Egre Doors & Wind GENERAL C The bedroom d LOCATION: Walls & Ceiling south ceiling an Floor: Ceiling Fan: Electrical:	OMMENTS loor did not lo CENTER L g: Satisfac Moisture rea around the Satisfac Typical cr N/A Switches: Open grou	d: N/A Operational: Locks/Latches ock well and the IVING ROOM ctory stains: c chimney chase ctory to M racks: Yes ind/Reverse po	☐ Yes ☐ Yes (see Operable: Soliding glass ☐ Marginal ☐ Yes ☐ Yes ☐ Satisfacto ☐ No ☐ No ☐ No ☐ larity:	✓ No note) ✓ Yes (so door did not) ory Outlets: ✓ Yes	□ No ee note) □ ot move well □ Poor □ No □ Poor ☑ No □ Margi ☑ Yes □ No ☑	Where: Corner Squeaks No Operates: Coverplates missing	Cracked Glass For east skylight and the □ Slopes T ✓ Yes □ No □ Safety Hazard
Bedroom Egro Doors & Wind GENERAL C The bedroom d LOCATION: Walls & Ceiling south ceiling ar Floor: Ceiling Fan: Electrical: Heating/Cooli	CENTER L g: Satisfac Moisture rea around the Satisfac Typical cr N/A Switches: Open groung Source:	d: N/A Operational: Locks/Latches ock well and the IVING ROOM ctory stains: c chimney chase ctory to M racks: Yes and/Reverse po Yes	☐ Yes ☐ Yes (see Operable: e sliding glass ☐ Marginal ☐ Yes ☐ Yes ☐ Satisfacto ☐ No larity: ☐ No	✓ No note) ✓ Yes (so door did no ory Outlets: ✓ Yes Holes:	□ No ee note) □ ot move well □ Poor □ No □ Poor ☑ No □ Margi ☑ Yes	Where: Corner Squeaks al Poo	Cracked Glass For east skylight and the □ Slopes T ✓ Yes □ No □ Safety Hazard
Bedroom Egre Doors & Wind GENERAL C The bedroom d LOCATION: Walls & Ceiling south ceiling ar Floor: Ceiling Fan: Electrical: Heating/Cooli Bedroom Egre	CENTER L g: Satisfac Moisture rea around the V Satisfac Typical cr N/A Switches: Open groung Source: ess Restricted	d: \Box N/A Operational: Locks/Latches ock well and the IVING ROOM ctory stains: c chimney chase ctory to M racks: Yes ud/Reverse po Yes d: M/A	☐ Yes ☐ Yes (see Operable: Solve Sliding glass ☐ Marginal ☐ Yes ☐ Satisfact ☐ No ☐ No ☐ Yes ☐ Yes	✓ No note) ✓ Yes (so door did not ory Outlets: ✓ Yes Holes: □ No	□ No ee note) □ ot move well □ Poor □ No □ Poor ☑ No □ Margi ☑ Yes □ No ☑	Where: Corner Squeaks No Operates: Coverplates missing	Cracked Glass To of east skylight and the □ Slopes To ✓ Yes □ No □ Safety Hazard
Bedroom Egro Doors & Wind GENERAL C The bedroom d LOCATION: Walls & Ceiling south ceiling ar Floor: Ceiling Fan: Electrical: Heating/Cooli	CENTER L g: Satisfac Moisture rea around the V Satisfac Typical cr N/A Switches: Open groung Source: ess Restricted	d: \Box N/A Operational: Locks/Latches lock well and the IVING ROOM etory stains: chimney chase ctory to M racks: Yes and/Reverse po Yes d: \Box N/A Operational:	☐ Yes ☐ Yes (see Operable: e sliding glass ☐ Marginal ☐ Yes ☐ Yes ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes	✓ No note) ✓ Yes (so door did no ory Outlets: ✓ Yes Holes: □ No □ No	□ No ee note) □ ot move well □ Poor □ No □ Poor ☑ No □ Margi ☑ Yes □ No ☑ □ Doors	Where: Corner Squeaks Inal Poo No Operates: Coverplates missing Walls Ceil	Cracked Glass Tof east skylight and the □ Slopes Together □ Safety Hazard Cracked Glass
Bedroom Egre Doors & Wind GENERAL C The bedroom d LOCATION: Walls & Ceiling south ceiling ar Floor: Ceiling Fan: Electrical: Heating/Cooli Bedroom Egre Doors & Wind	CENTER L g: Satisfac Moisture rea around the Satisfac Typical cr N/A Switches: Open grou ng Source: ess Restricted lows:	d: N/A Operational: Locks/Latches ock well and the IVING ROOM ctory stains: c chimney chase ctory to M racks: Yes and/Reverse po Yes d: N/A Operational: Locks/Latches	☐ Yes ☐ Yes (see Operable: e sliding glass ☐ Marginal ☐ Yes ☐ Yes ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes	✓ No note) ✓ Yes (so door did not ory Outlets: ✓ Yes Holes: □ No	□ No ee note) □ ot move well □ Poor □ No □ Poor ☑ No □ Margi ☑ Yes □ No ☑	Where: Corner Squeaks No Operates: Coverplates missing	Cracked Glass Tof east skylight and the □ Slopes Together □ Safety Hazard Cracked Glass
Bedroom Egre Doors & Wind GENERAL Common description of the bedroom description of the bedroom description of the bedroom description of the bedroom electrical: Heating/Cooling Bedroom Egre Doors & Wind GENERAL Common description of the bedroom electrical:	OMMENTS CENTER L G: Satisfac Moisture rea around the Satisfac Typical cr N/A Switches: Open groung Source: ess Restricted lows:	d: \Box N/A Operational: Locks/Latches ock well and the IVING ROOM ctory stains: c chimney chase ctory to \Box M racks: Yes and/Reverse po Yes d: \Box N/A Operational: Locks/Latches	☐ Yes ☐ Yes (see Operable: e sliding glass ☐ Marginal ☐ Yes ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes	✓ No note) ✓ Yes (so door did not) Ory Outlets: ✓ Yes Holes: □ No □ No ✓ Yes	□ No ee note) □ ot move well □ Poor □ No □ Poor ☑ No □ Margi ☑ Yes □ No ☑ □ Doors □ No	Where: Corner Squeaks A Operates: Coverplates missing Walls Missing Crac	Cracked Glass Tof east skylight and the □ Slopes Together □ Safety Hazard Cracked Glass

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 13 of 47



LOCATION: EAST BEDROOM	
Walls & Ceiling: ☑ Satisfactory to ☑ Marginal	□ Poor
Moisture stains: \square Yes	✓ No Where:
Floor: ✓ Satisfactory to ✓ Marginal	☐ Poor ☐ Squeaks ☐ Slopes
Typical cracks:	☑ No
Ceiling Fan: ☐ N/A ☑ Satisfactory	☐ Marginal ☐ Poor
	utlets: ☑ Yes ☐ No Operates: ☑ Yes ☐ No
	Yes \square No \square Coverplates missing \square Safety Hazard
1 9 _ 1	oles: ☐ Doors ☐ Walls ☐ Ceilings
	No
Doors & Windows: Operational: ✓ Yes	No
Locks/Latches Operable: ✓	Yes □ No □ Missing □ Cracked Glass
GENERAL COMMENTS	
GENERAL COMMENTS	
LOCATION: CENTER ROOM WITH NO WINDOW	
Walls & Ceiling: ☑ Satisfactory to ☑ Marginal	□ Poor
Moisture stains: \square Yes	✓ No Where:
Floor: ✓ Satisfactory to ✓ Marginal	☐ Poor ☐ Squeaks ☐ Slopes
Ceiling Fan: ☑ N/A ☐ Satisfactory	☐ Marginal ☐ Poor
9	utlets: ☑ Yes ☐ No Operates: ☑ Yes ☐ No
	uners. I res I no Oberates. I res I no
	<u>.</u>
Open ground/Reverse polarity: ✓	_
Open ground/Reverse polarity: Heating/Cooling Source: Yes □ No Ho	Yes
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings
Open ground/Reverse polarity: Heating/Cooling Source: Yes □ No Ho Bedroom Egress Restricted: N/A □ Yes □ Doors & Windows: Operational: Yes □	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Bedroom Egress Restricted: ✓ N/A ☐ Yes Doors & Windows: Operational: ✓ Yes Locks/Latches Operable: ✓	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Bedroom Egress Restricted: ✓ N/A ☐ Yes Doors & Windows: Operational: ✓ Yes Locks/Latches Operable: ✓ GENERAL COMMENTS	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Bedroom Egress Restricted: ✓ N/A ☐ Yes Doors & Windows: Operational: ✓ Yes Locks/Latches Operable: ✓	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Bedroom Egress Restricted: ✓ N/A ☐ Yes Doors & Windows: Operational: ✓ Yes Locks/Latches Operable: ✓ GENERAL COMMENTS	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No
Open ground/Reverse polarity: Heating/Cooling Source: Yes No Ho Bedroom Egress Restricted: N/A Yes Doors & Windows: Operational: Yes Locks/Latches Operable: GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: Satisfactory Marginal	Yes
Open ground/Reverse polarity: Heating/Cooling Source: Yes No Ho Bedroom Egress Restricted: Operational: Yes Doors & Windows: Operational: Yes Locks/Latches Operable: GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings No No Yes □ No □ Missing □ Cracked Glass □ Poor □ No Where:
Open ground/Reverse polarity: Heating/Cooling Source: Yes No Ho Bedroom Egress Restricted: Operational: Locks/Latches Operable: GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: Satisfactory Moisture stains: Yes Floor: Marginal	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings No No Yes □ No □ Missing □ Cracked Glass □ Poor □ No Where: □ Poor □ Squeaks □ Slopes
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐ Doors & Windows: Operational: ✓ Yes ☐ Locks/Latches Operable: ✓ GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: ✓ Satisfactory ☐ Marginal Moisture stains: ☐ Yes Floor: ✓ Satisfactory ☐ Marginal Ceiling Fan: ☐ N/A ✓ Satisfactory	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Missing □ Cracked Glass □ Poor □ No □ Where: □ Poor □ Squeaks □ Slopes □ Marginal □ Poor
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐ Doors & Windows: Operational: ✓ Yes ☐ Locks/Latches Operable: ✓ GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: ✓ Satisfactory ☐ Marginal Moisture stains: ☐ Yes Floor: ✓ Satisfactory ☐ Marginal Ceiling Fan: ☐ N/A Satisfactory Electrical: Switches: ✓ Yes ☐ No Output Doors & Windows: ✓ Yes ☐ No Output Doors & Windows: ✓ Yes ☐ No Output Doors & Washington ☐ N/A Output Doors & Windows: ✓ Yes ☐ No Output Doors & Windows: ☐ Yes ☐ Yes ☐ No Output Doors & Windows: ☐ Yes	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings No No Yes □ No □ Missing □ Cracked Glass □ Poor □ No Where: □ Poor □ Squeaks □ Slopes □ Marginal □ Poor utlets: ☑ Yes □ No Operates: ☑ Yes □ No
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐ Doors & Windows: Operational: ✓ Yes ☐ Locks/Latches Operable: ✓ GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: ✓ Satisfactory ☐ Marginal Moisture stains: ☐ Yes Floor: ✓ Satisfactory ☐ Marginal Ceiling Fan: ☐ N/A ✓ Satisfactory Electrical: Switches: ✓ Yes ☐ No Ou Open ground/Reverse polarity: ☐	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings No No Yes □ No □ Missing □ Cracked Glass □ Poor □ No Where: □ Poor □ Squeaks □ Slopes □ Marginal □ Poor utlets: ☑ Yes □ No Operates: ☑ Yes □ No Yes ☑ No □ Coverplates missing □ Safety Hazard
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐ Doors & Windows: Operational: ✓ Yes ☐ Locks/Latches Operable: ✓ GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: ✓ Satisfactory ☐ Marginal Moisture stains: ☐ Yes Floor: ✓ Satisfactory ☐ Marginal Ceiling Fan: ☐ N/A ✓ Satisfactory Electrical: Switches: ✓ Yes ☐ No Ou Open ground/Reverse polarity: ☐ Heating/Cooling Source: ✓ Yes ☐ No Ho	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings No No Yes □ No □ Missing □ Cracked Glass □ Poor □ No Where: □ Poor □ Squeaks □ Slopes □ Marginal □ Poor utlets: ☑ Yes □ No Operates: ☑ Yes □ No I Yes ☑ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐ Doors & Windows: Operational: ✓ Yes ☐ Locks/Latches Operable: ✓ GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: ✓ Satisfactory ☐ Marginal Moisture stains: ☐ Yes Floor: ✓ Satisfactory ☐ Marginal Ceiling Fan: ☐ N/A ✓ Satisfactory Electrical: Switches: ✓ Yes ☐ No Open ground/Reverse polarity: ☐ Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Missing □ Cracked Glass □ Poor □ No □ Where: □ Poor □ Squeaks □ Slopes □ Marginal □ Poor □ Marginal □ Poor □ Squeaks □ Slopes □ Marginal □ Poor □ Squeaks □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ Safety Hazard oles: □ Doors □ Walls □ Ceilings
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐ Doors & Windows: Operational: ✓ Yes ☐ Locks/Latches Operable: ✓ GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: ✓ Satisfactory ☐ Marginal Moisture stains: ☐ Yes Floor: ✓ Satisfactory ☐ Marginal Ceiling Fan: ☐ N/A ☐ Satisfactory Electrical: Switches: ✓ Yes ☐ No Ou Open ground/Reverse polarity: ☐ Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐ Doors & Windows: Operational: ✓ Yes ☐	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Missing □ Cracked Glass □ Poor □ No □ Where: □ Poor □ Squeaks □ Slopes □ Marginal □ Poor □ Marginal □ Poor □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings
Open ground/Reverse polarity: Heating/Cooling Source: Yes No Ho Bedroom Egress Restricted: N/A Yes Doors & Windows: Operational: Yes Locks/Latches Operable: GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: Satisfactory Marginal Moisture stains: Yes Floor: Satisfactory Marginal Ceiling Fan: N/A Satisfactory Electrical: Switches: Yes No Ou Open ground/Reverse polarity: Heating/Cooling Source: Yes No Ho Bedroom Egress Restricted: N/A Yes Doors & Windows: Operational: Yes Locks/Latches Operable: ✓	Yes
Open ground/Reverse polarity: Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐ Doors & Windows: Operational: ✓ Yes ☐ Locks/Latches Operable: ✓ GENERAL COMMENTS Room had no window. LOCATION: EAST LIVING ROOM OF ADDITION Walls & Ceiling: ✓ Satisfactory ☐ Marginal Moisture stains: ☐ Yes Floor: ✓ Satisfactory ☐ Marginal Ceiling Fan: ☐ N/A ☐ Satisfactory Electrical: Switches: ✓ Yes ☐ No Ou Open ground/Reverse polarity: ☐ Heating/Cooling Source: ✓ Yes ☐ No Ho Bedroom Egress Restricted: ✓ N/A ☐ Yes ☐ Doors & Windows: Operational: ✓ Yes ☐	Yes □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Missing □ Cracked Glass □ Poor □ No □ Where: □ Poor □ Squeaks □ Slopes □ Marginal □ Poor □ Marginal □ Poor □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings □ No □ Coverplates missing □ Safety Hazard oles: □ Doors □ Walls □ Ceilings

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 14 of 47



LOCATION: SE BEDROOM								
Walls & Ceiling: ✓ Satisfactory								
Moisture stains:	☐ Yes		☑ No	Where:				
Floor:	☐ Marginal		☐ Poor	☐ Squeaks	☐ Slopes			
Ceiling Fan: ☐ N/A	✓ Satisfactor	ory to 🗹	Marginal	☐ Poo:	r			
Electrical: Switches: ✓ Yes	□ No	Outlets:	✓ Yes □	No Operates:	✓ Yes □ No			
Open ground/Rev	erse polarity:	☐ Yes	☑ No ☐ C	overplates missing	☐ Safety Hazard			
Heating/Cooling Source:	✓ No	Holes:	□ Doors □	☐ Walls ☐ Ceil	ings			
Bedroom Egress Restricted:	N/A □ Yes	□ No						
Doors & Windows: Operat	ional: 🗹 Yes	□ No						
Locks/	Latches Operable:	Yes	☑ No (see no	te)	sing			
Glass								
GENERAL COMMENTS								
Door did not latch, repair as necessar	ıry.							
LOCATION: SOUTH BEDROO	M							
Walls & Ceiling: ✓ Satisfactory	☐ Marginal		☐ Poor					
Moisture stains:	☐ Yes		☑ No	Where:				
Floor:			☐ Poor	☐ Squeaks	✓ Slopes			
Ceiling Fan: □ N/A	✓ Satisfactor	ory to 🗹	Marginal	□ Poo	r			
Electrical: Switches: ✓ Yes	□ No	Outlets:	✓ Yes □	No Operates:	✓ Yes □ No			
Open ground/Rev	erse polarity:	☐ Yes	☑ No ☐ C	overplates missing	☐ Safety Hazard			
Heating/Cooling Source: ✓ Yes		Holes:	□ Doors □	∃ Walls □ Ceil	ings			
Bedroom Egress Restricted: □	N/A □ Yes	✓ No						
Doors & Windows: Operat	ional: 🗹 Yes	□ No						
Locks/	Latches Operable:	Yes	□ No □ Mis	ssing	cked Glass			
GENERAL COMMENTS								

The bedroom door did not lock well and the sliding glass door did not move well, repair as necessary.

Note: Signs of shifting/settlement were noted throughout the older portion of the house and the SW corner of old foundation had moved considerably (more than an inch) with the west wall appearing to be kicked outward toward the bottom. The inside corner of the room was not very visible due to an installed dresser. The movement was severe enough for this home inspector to recommend it be reviewed by a structural engineer. The current home owners had already hired structural engineers a couple of months ago and the engineers thoughts were that the structure was done shifting/settling except for the slight ground movement associated with the dry and wet seasons (ground shrinks and swells).

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 15 of 47



	✓ Satisfactory	☐ Marg	•		□ Needs repair	
	☐ Representative nu				(See remarks pag	
Evidence of Leaking	_				Needed: ✓ Yes	
☐ Glazing compou			☐ Hardware mis		ken counter-balar	
Security Bars Prese	nt: ☐ Yes ☑ N	No	ested \square Safety	hazard \square Test	release mechanism	before moving in
		tion(s): Center	Living room			
	(Not Tested) 🗹 Wood		lburner stove (See		☐ Electric	☐ Ventless
Material:	✓ Masoı		l (pre-fabricated)		_	_
Miscellaneous:				•	r operates:	
•	i joints or cracks in				place doors missi	-
Hearth Adequate:			✓ N/A ☐ Satisfa	•	-	se/missing
Physical Condition					naving flue cleaned	
STAIRS / STEPS /			Satisfactory	☐ Marginal	□ Poor	✓ None
Handrail:		•	Marginal	□ Poor	☐ Safety hazard	
Risers/Treads:	☐ Satisfa	tactory L] Marginal	☐ Poor	\square Risers/Tread	s uneven
SMOKE / CARBO	ON MONOXIDE I	DETECTORS	(See remarks	page)		
Present:	Smoke Detector:			Operates:	✓ Yes □ No	☐ Not tested
	CO Detector:	✓ Yes	□ No	Operates:	✓ Yes □ No	☐ Not tested
ATTIC/STRUCTU	URE/FRAMING/I	INSULATION	□ N/A			
Access:	☐ Stairs ☑	1 Pulldown	☐ Scuttlehole/Hat	tch	access	er
Inspected From:	☐ Access panel	✓ In the	e attic	☐ Other		
Location:	☐ Bedroom hall	☐ Bedro	oom closet	☐ Garage	Other	
Flooring:	☐ Complete	Partia		□ None		
Insulation:	Type: Fiberglass				3-6 Approx. R-r	
	-	Displaced			☐ Recommend	Baffles @ Eaves
Installed In:		Walls	☐ Between ceili	ng joists	☐ Not visible	
Vantilations	✓ Recommend at			additional vontila		
Ventilation: Fans Exhausted To:	✓ Ventilation app	attic: \(\square \) Yes	✓ No	Outside: 🗹 Yes		visible
HVAC Duct:	☐ Satisfactory ☐		\square Split	☐ Disconnected		✓ <i>Not visible</i>
	-	Satisfactory	□ Needs repair		i 🗀 Leaking	- I voi visioic
Structural Probler		•	□ Recommend		ommend Structur	al Engineer
Roof Structure:	✓ Rafters	Trusses	☑ Wood	☐ Metal	☐ Other	o .
Collar Ties Present:	☐ Yes ☑	₫ No	□ N/A			
Roof Sheathing:	•	I OSB	☑ lx Wood	\square Rotted	\square Stained	☐ Delaminated
Evidence of Conde		_	✓ Yes	□ No (See re	marks page)	
Ceiling Joists:		Metal _	☐ Other	☐ Not visible	_	
Vapor Barriers:	✓ Kraft/foil faced			☐ Not visible	☐ Improperly in	nstalled
Firewall Between Un			□ Needs repair/	-	marks page)	7.7
Electrical:	<u>Upen junction</u>	ı vox(es)	⊔ Handyman w	ırıng	□ Visible knob-	-and-tube
GENERAL COMMENTS						
Electrical: \square Open junction box(es) \square Handyman wiring \square Visible knob-and-tube						

The fireplace had an older gas line dismantled and no longer in use.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 16 of 47



WATER SERVICE	Main Shut-o	ff Location: Front	yard		
Water Entry Piping:	☐ Not visible	✓ Copper/Galv.	☐ Plastic* (PVC	, CPVC, Polybutylene, I	PEX) 🗆 Unknown
Visible Water Distributi	on Piping: 🗹 Copp	per Galvanized	☐ Plastic* (PVC	, CPVC, Polybutylene, I	PEX) 🗆 Unknown
Condition:	Satisfactory	☐ Marginal	□ Poor		
Lead Other Than Solde	r Joints: ☐ Yes	☑ No	☐ Unknown	☐ Service entry	
Functional Flow:	Adequate	□ Poor	☑ Water pressu	re over 80 psi	
Pipes, Supply/Drain:	☐ Corroded	\square Leaking	☐ Valves broke	n/missing 🔽 D	issimilar metal
Drain/Waste/Vent Pipe		✓ Cast iron	✓ Galvanized	✓ PVC □ A	BS
Condition:	✓ Satisfactory	✓ Marginal	□ Poor	Cross connection	: □ Yes ☑ No
Traps Proper P-Type	•	✓ Yes	□ No	□ P-traps recomm	nended
Functional Drainage:		□ Poor	☐ Recommend	plumber evaluate	
Interior Fuel Storage		☑ No	Leaking: Yes	•	
Gas Line:	☐ Copper	☐ Brass	☑ Black iron	☐ Stainless steel	☐ CSST ☐ Not visible
Condition:	✓ Satisfactory 1	Marginal	□ Poor		
	<u> </u>				
MAIN FUEL SHUT-	OFF LOCATION	Unknown	□ N/A		
WELL PUMP	☑ N/A	☐ Submersible			
Location:	☐ In basement	☐ Well house	☐ Well pit	☐ Shared well	
Pressure Gauge Oper		□ No	☐ Unknown		psi Not visible
			□ Clikilowii	wen pressure	psi iii Not visiole
SANITARY / GRIND		☑ N/A			_
Sealed Crock:	☐ Yes ☐ No	Check Valve:	☐ Yes ☐ No	Vented:	☐ Yes ☐ No
WATER HEATER #1	□ N/A	Condition:	✓ Satisfactory	to Marginal	□ Poor
Brand name:		Heater Company	Serial #: 1007T	•	_ 1 0 0 1
Type:	☑ Gas	☐ Electric	□ Oil	☐ Other	
Unit Elevated:	☐ Yes ☑ No	□ N/A	-	corroded/leaking	
Capacity:	50 gallons	"	Approximate age		
Combustion Air Venting		□ No □ N/A	Seismic restraint		□ No ☑ N/A
Relief Valve:	✓ Yes □ No		oer: □ Yes ☑		☑ Recommend repair
Vent Pipe:		tisfactory \square Pitch pr			☐ Recommend repair
		,			•
WATER HEATER #2 Brand name:		Condition:	✓ Satisfactory Serial #: 0947T		□ Poor
	Whirlpool ☐ Gas	✓ Electric	Serial #: 094/1	□ Other	
Type:	☐ Yes ☐ No	✓ N/A	_ 0.11		
Unit Elevated:				corroded/leaking	2 (.)
Capacity:			□ No	Approximate age:	
Combustion Air Venting					
Relief Valve:	✓ Yes □ No		per: ✓ Yes □		☐ Recommend repair
Vent Pipe:	✓ N/A □ Sa	tisfactory	roper \square <i>Imprope</i>	r □ Rusted	☐ Recommend repair
WATER SOFTENER	(Unit not ev	aluated) 🗹 None f	ound		
Loop Installed:	\square Yes \square No	Plumbing Hoo	ked Up: □ Yes	□ No	
Softener Present:	☐ Yes ☐ No	Plumbing Leal	king: ☐ Yes	□ No	
GENERAL COMMENTS					
OEI (ERITE COI)II/IE	N15				
The gas fired water hea		ure/pressure valve e	xtension that neck	ed down to a smalle	er size, recommend a

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 17 of 47



HEATING SYSTEM	- UNIT #1 _ Lo	cation: Hallway clos	set	(5	See remarks page)
Brand Name:	Bryant			e: 9-18+ year(s)	□ Unknown
	Model #: 331AA		Serial #: 380085		
Energy Source:	☑ Gas	□ LP	□ Oil	☐ Electric	☐ Solid Fuel
Warm Air System:	☐ Belt drive	☑ Direct drive	☐ Gravity		n ☐ Floor/Wall unit
Heat Exchanger:		✓ Visual w/mirror			☐ Carbon/soot buildup
Carbon Monoxide:	□ N/A	☐ Detected at Plea	-	☐ Not tested	_
CO Test:	Tester: TIFF 880		bustion Air Venting		□ No □ N/A
Controls:	Disconnect: 🗹		ormal operating ar		
Distribution:	✓ Metal duct	☐ Insul. flex duct			☐ Asbestos-like wrap
Flue Piping:	□ N/A		nproper slope	☐ Safety hazard	d
Supports for Piping/In		\square N/A \square Y			_
Filter:	✓ Standard	☐ Electrostatic			g/replacement
When Turned On By					□ No □ Not tested
Heat Pump:		☐ Aux. gas ☑ N		ducts: ✓ Yes	□ No □ N/A
System Not Operated I	Due To:	Exterior temperature	☐ Other		
☐ Recommend techni	cian examine	System Condition:	Satisfactory	to Marginal	□ Poor
HEATING SYSTEM	- UNIT #2 Loc	cation: Shop		(5	See remarks page)
Brand Name:	Goodman		Approximate age		☐ Unknown
	Model #: ARUF		Serial #: 091009		_
Energy Source:	☐ Gas	□ LP	□ Oil	✓ Electric	☐ Solid Fuel
Warm Air System:	☐ Belt drive	✓ Direct drive	☐ Gravity		n □ Floor/Wall unit
Heat Exchanger:	✓ N/A (sealed)	☐ Visual w/mirror			☐ Carbon/soot buildup
Carbon Monoxide:	☑ N/A	☐ Detected at Plea	· ·	☐ Not tested	
CO Test:	Tester:		bustion Air Venting		□ No ☑ N/A
Controls:	Disconnect: 🗹		ormal operating ar		
Distribution:	☐ Metal duct	☑ Insul. flex duct			☐ Asbestos-like wrap
Flue Piping:	☑ N/A		nproper slope	☐ Safety hazard	d
Supports for Piping/In		\square N/A \square Y			_
Filter:	✓ Standard	☐ Electrostatic	✓ Satisfactory	•	g/replacement
				•	es 🗆 No 🗹 Not tested
Heat Pump:		☐ Aux. gas ☐ N		ducts: ☐ Yes	☑ No □ N/A
System Not Operated I		Exterior temperature			
☐ Recommend techni	cian examine	System Condition:	Satisfactory	☐ Marginal	□ Poor
OTHER SYSTEMS	✓ N/A	□ El	lectric baseboard	☐ Radiant ceiling	g cable
	☐ Gas space hea	iter	oodburning stove	(See Remarks po	age)
Proper Operation:	☐ Yes	□ No			
System Condition:	☐ Satisfactory	☐ Marginal ☐ Po	oor		
GENERAL COMME	NTS				
Furnace #1 was a model that had been manufactured from 1993 to 2002, thus the approximate age was from 9-19 yrs. It					
appeared to be in normal working order at the time of the inspection. Heat exchanger had limited visibility due to its high-					
efficiency design. Flue was drafting properly at the time of the inspection. Filter should be changed monthly.					
Furnace #2: The heat p					
•	- •	_	-	-	
The closet where furnace #1 and water heater #1 are located have combustion venting cut into the bottom of both door. Recommend a licensed HVAC technician evaluate the need for additional combustion venting when next serviced.					

Recommend keeping a regular maintenance schedule on the furnace and A/C units and components.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 18 of 47

	ASD.	ELECTRIC	COOLING SYSTEM	
MAIN PANEL Loca	ation: North Family	Room	Condition: \square Satisfactor	y ☑ Marginal
Adequate Clearance T	· · · · · · · · · · · · · · · · · · ·			☐ Breakers ☐ Fuses
Appears Grounded:	✓ Yes □ No	□ Not visible	ge. 100	— 2100000
G.F.C.I. present:	☐ Yes ☑ No	Operati	ive:	
A.F.C.I. present:	☐ Yes ☑ No	Operati		
MAIN WIRE:	☐ Copper	✓ Aluminum		☐ Not visible
	☐ Tapping before		☐ Double tapping of the main w	
Condition:	☐ Satisfactory	✓ Marginal	☐ Federal Pacific Panel Stab Lol	
BRANCH WIRE:	☑ Copper	✓ Aluminum*		☐ Not visible
Condition:	☐ Satisfactory	□ Poor	☑ Recommend electrician evalu	uate/repair*
	✓ Romex	☐ BX cable	☐ Conduit	☐ Knob & tube**
	☑ Double tapping	\square Wires	undersized/oversized breaker/fus	e
SUB PANEL(S)	None apparent		•	
Location 1:	Loc	cation 2:	Location 3:	
	☐ Panel not access	sible	valuated	
Branch Wire:	☐ Copper	☐ Aluminum	☐ Copper clad aluminum	
Neutral/ground separated:		Neutral isolated:	☐ Yes ☐ No ☐ Safety haz	ard
ELECTRICAL FIXT	URES			
		g fixtures, switches, a	nd receptacles located inside the h	ouse, garage, and exterior
walls were tested and for			_	
Condition:	✓ Satisfactory	☐ Marginal	Poor	
	Open grounds		☑ GFCIs not operating	
	☑ Ungrounded 3-p	orong outlets	☑ Recommend electrician evalu	uate/repair*
GENERAL COMME	NTS			
		or more. The main el	lectrical panel cover was missing,	no fuses were labeled,
			ing was is use - potential safety ha	
may need to be upgrade	100.			Edias. I dilei was fall dile
			d electrician further evaluate the e	
any necessary repairs.	No signs of overheat	ing were evident at th	e time of the inspection.	lectrical system and make
any necessary repairs. COOLING SYSTEM	No signs of overheat – UNIT #1	ing were evident at the Central system Locati	te time of the inspection. ion: Attached to furnace in closet	lectrical system and make
any necessary repairs. COOLING SYSTEM Energy Source:	No signs of overheat – UNIT #1 ☑ C ☐ Electric	ing were evident at the Central system Location Gas	ion: Attached to furnace in closet Water	Age: Unknown
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type:	No signs of overheat - UNIT #1 ☑ C □ Electric □ Air cooled	ing were evident at the Central system Locati ☐ Gas ☐ Water cooled	ion: Attached to furnace in closet Water	lectrical system and make Age: Unknown
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil:	No signs of overheat - UNIT #1 ☑ C □ Electric □ Air cooled □ Satisfactory	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed	te time of the inspection. ion: Attached to furnace in closet Water	Age: Unknown I □ Heat pump
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines:	No signs of overheat UNIT #1 ☑ C □ Electric □ Air cooled □ Satisfactory □ Leak	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed ☐ Damage	te time of the inspection. ion: Attached to furnace in closet Water Other Gas chiller Geotherma Needs cleaning Damaged Insulation missing	Age: Unknown
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain:	No signs of overheat - UNIT #1	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed	te time of the inspection. ion: Attached to furnace in closet Water	Age: Unknown I □ Heat pump
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines:	No signs of overheat UNIT #1 Electric Air cooled Satisfactory Leak To exterior Differential: 18°F	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed ☐ Damage ☐ To pump	te time of the inspection. ion: Attached to furnace in closet Water Other Gas chiller Geotherma Needs cleaning Damaged Insulation missing Floor drain Other	Age: Unknown Il □ Heat pump ✓ Satisfactory
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation:	No signs of overheat UNIT #1	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed ☐ Damage ☐ To pump erature (split) should be	te time of the inspection. ion: Attached to furnace in closet Water Other Gas chiller Geotherman Needs cleaning Damaged Insulation missing Floor drain Other be 14-22° Fahrenheit (See remark)	Age: Unknown Il □ Heat pump ✓ Satisfactory
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition:	No signs of overheat UNIT #1	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed ☐ Damage ☐ To pump	te time of the inspection. ion: Attached to furnace in closet Water Other Gas chiller Geotherma Needs cleaning Damaged Insulation missing Floor drain Other	Age: Unknown Il □ Heat pump ✓ Satisfactory
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMME	No signs of overheat UNIT #1 Electric Air cooled Satisfactory Leak To exterior Differential: 18°F Difference in tempo Satisfactory Satisfactory	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed ☐ Damage ☐ To pump erature (split) should I ☐ Marginal	te time of the inspection. ion: Attached to furnace in closet Water Other Gas chiller Geotherman Needs cleaning Damaged Insulation missing Floor drain Other be 14-22° Fahrenheit (See remark	Age: Unknown Il □ Heat pump ✓ Satisfactory ks page)
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMMERCOOLING SYSTEM	No signs of overheat UNIT #1	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed ☐ Damage ☐ To pump Perature (split) should Ion Marginal Central system Location	te time of the inspection. ion: Attached to furnace in closet Water Other Gas chiller Geotherman Needs cleaning Damaged Insulation missing Floor drain Other be 14-22° Fahrenheit (See remark	Age: Unknown Il □ Heat pump ✓ Satisfactory ks page)
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMMER COOLING SYSTEM Energy Source:	No signs of overheat UNIT #1	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed ☐ Damage ☐ To pump Perature (split) should Ion Marginal Central system Location Gas	te time of the inspection. ion: Attached to furnace in closet Water Other Gas chiller Geotherman Needs cleaning Damaged Insulation missing Floor drain Other be 14-22° Fahrenheit (See remark Poor	Age: Unknown Il
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMME COOLING SYSTEM Energy Source: Unit Type:	No signs of overheat UNIT #1	ing were evident at the Central system Location Gas Gas Water cooled Not visible/sealed Damage To pump erature (split) should be Marginal Central system Location Gas Water cooled	time of the inspection. ion: Attached to furnace in closet Water	Age: Unknown Il
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMME COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil:	No signs of overheat - UNIT #1	ing were evident at the Central system Located Gas Gas Water cooled ✓ Not visible/sealed Damage To pump To pump To pump To pump Central system Located Gas Gas Water cooled ✓ Not visible/sealed ✓ Not visible/sealed	te time of the inspection. ion: Attached to furnace in closet Water	lectrical system and make Age: Unknown Il □ Heat pump ✓ Satisfactory ks page) op Age: 2+ yrs Il ☑ Heat pump
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMMET COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines:	No signs of overheat UNIT #1	ing were evident at the Central system Location Gas ☐ Water cooled ☑ Not visible/sealed ☐ Damage ☐ To pump erature (split) should Ion Marginal Central system Location Gas ☐ Water cooled ☑ Not visible/sealed ☐ Damage	te time of the inspection. ion: Attached to furnace in closet Water	Age: Unknown Il
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMMET COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain:	No signs of overheat - UNIT #1	ing were evident at the Central system Located Gas Gas Water cooled ✓ Not visible/sealed Damage To pump To pump To pump To pump Central system Located Gas Gas Water cooled ✓ Not visible/sealed ✓ Not visible/sealed	te time of the inspection. ion: Attached to furnace in closet Water	lectrical system and make Age: Unknown Il □ Heat pump ✓ Satisfactory ks page) op Age: 2+ yrs Il ☑ Heat pump
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMMET COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines:	No signs of overheat UNIT #1 Electric Air cooled Satisfactory Leak To exterior Differential: 18°F Difference in tempo Satisfactory NTS UNIT #1 Electric Air cooled Satisfactory Leak To exterior Differential: 16°F	ing were evident at the Central system Location Gas Water cooled Not visible/sealed Damage To pump To pump Central system Location Gas Water cooled Not visible/sealed Damage To pump	tion: Attached to furnace in closet Water	Age: Unknown Il □ Heat pump ✓ Satisfactory ks page) op Age: 2+ yrs Il ☑ Heat pump ✓ Satisfactory
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMMENTE COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation:	No signs of overheat UNIT #1	ing were evident at the Central system Location Gas Water cooled Not visible/sealed Damage To pump To pump Central system Location Gas Water cooled Not visible/sealed Damage To pump To pump	tion: Attached to furnace in closet Water	Age: Unknown Il □ Heat pump ✓ Satisfactory ks page) op Age: 2+ yrs Il ☑ Heat pump ✓ Satisfactory
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMMET COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain:	No signs of overheat UNIT #1 Electric Air cooled Satisfactory Leak To exterior Differential: 18°F Difference in tempo Satisfactory NTS UNIT #1 Electric Air cooled Satisfactory Leak To exterior Differential: 16°F	ing were evident at the Central system Location Gas Water cooled Not visible/sealed Damage To pump To pump Central system Location Gas Water cooled Not visible/sealed Damage To pump	tion: Attached to furnace in closet Water	Age: Unknown Il □ Heat pump ✓ Satisfactory ks page) op Age: 2+ yrs Il ☑ Heat pump ✓ Satisfactory
any necessary repairs. COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation: Condition: GENERAL COMMENTE COOLING SYSTEM Energy Source: Unit Type: Evaporator Coil: Refrigerant lines: Condensate Line/Drain: Operation:	No signs of overheat UNIT #1	ing were evident at the Central system Location Gas Water cooled Not visible/sealed Damage To pump To pump Central system Location Gas Water cooled Not visible/sealed Damage To pump To pump	tion: Attached to furnace in closet Water	Age: Unknown Il □ Heat pump ✓ Satisfactory ks page) op Age: 2+ yrs Il ☑ Heat pump ✓ Satisfactory

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 19 of 47



ITEMS NOT OPERATING

The master bathroom toilet appeared to be continually filling.

MAJOR CONCERNS

Item(s) that have failed or have potential of failing soon.

None apparent.

POTENTIAL SAFETY HAZARDS

Any electrical outlets that are not GFCI protected on the exterior, in the kitchen or bathrooms.

The main electrical wires were only about 5 feet above a portion of the deck.

The main electrical panel cover was missing, no fuses were labeled, some fuse amperages were unknown and apparent aluminum wiring was is use.

Any missing covers on electrical outlet, light switches or electrical junction boxes.

Any non-tempered windows within shower stall.

DEFERRED COST ITEMS

Items that have reached or are reaching their normal life expectancy or show indications that they may require repair or replacement <u>anytime during the next five (5) years</u>.

Furnace that is 13+ years. A/C that is 7+ years.

* Items listed in this report may inadvertently have been left off the Summary Sheet. Customer should read the entire report, including the Remarks.



Figure 1: On the surface the deck appeared to be in good shape.



Figure 2: Some areas under the seats were rotted and in need of repair.



Figure 3: Loose electrical outlet in the attic.




Figure 4: Electrical junction box in the attic without a cover.



Figure 5: Electrical service wires covering was flaking/unraveling.



Figure 6: Gap to seal at the base of the electrical masthead.



Figure 7: Facia with peeling paint.



Figure 8: Soffit with peeling paint. This type of peeling may indicate that moisture is getting on the backside of the soffit.



Figure 9: Chimney chase flashing in need of repair.



Figure 10: Area of moisture penetration at ceiling and fireplace connection.



Figure 11: Large energized electrical lines run outside the siding and not run in conduit.



Figure 12: Electrical line sharing a wall penetration on the east exterior. The electrical wire was tested and the line was not energized at that time it was tested.



Figure 13: Settlement/shifting of the SW corner of the original foundation (outside master bedroom).



Figure 14: Wall appeared to be kicked out towards the bottom.



Figure 15: Dip in roof line and attached gutter.



Figure 16: Wood siding in contact with the soil.



Figure 17: Low area next to the foundation.



Figure 18: Water heater #1 with a necked down temperature/pressure valve extension.



Figure 19: Wire insulation wearing where it wrapped around this disconnect box of A/C compressor #1.



Figure 20: Apparent solid strand aluminum wire next to an apparent copper wire.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 24 of 47



REMARKS

SERVICE WALKS/DRIVEWAYS

Spalling concrete cannot be patched with concrete because the new will not bond with the old. Water will freeze between the two layers, or the concrete will break up from movement or wear. Replacement of the damaged section is recommended. Walks or driveways that are close to the property should be properly pitched away to direct water away from the foundation. Asphalt driveways should be kept sealed and larger cracks filled so as to prevent damage from frost.

Patios that have settled towards the structure should be mudjacked or replaced to assure proper pitch. Improperly pitched patios are one source of wet basements.

EXTERIOR WOOD SURFACES

All surfaces of untreated wood need regular applications of paint or special chemicals to resist damage. Porch or deck columns and fence posts which are buried in the ground and made of untreated wood will become damaged within a year or two.

Decks should always be nailed with galvanized, stainless steal or aluminum nails. Decks that are not painted or stained should be treated with a water sealer.

GRADING AND DRAINAGE

Any system of grading or landscaping that creates positive drainage (moving water away from the foundation walls) will help to keep a basement dry. Where negative grade exists and additional backfill is suggested, it may require digging out around the property to get a proper pitch. Dirt shall be approximately 6" below the bottom sill and should not touch wood surfaces.

Flower beds, loose mulched areas, railroad ties and other such landscaping items close to the foundation trap moisture and contribute to wet basements. To establish a positive grade, a proper slope away from the house is 1" per foot for approximately 5-6 feet. Recommend ground cover planting or grass up to foundation.

ROOF AND SURFACE WATER CONTROL

Roof and surface water must be controlled to maintain a dry basement. This means keeping gutters cleaned out and aligned, extending downspouts, installing splashblocks, and building up the grade so that roof and surface water is diverted away from the building.

WINDOW WELLS

The amount of water which enters a window well from falling rain is generally slight, but water will accumulate in window wells if the yard is improperly graded. Plastic window well covers are useful in keeping out leaves and debris.

RETAINING WALLS

Retaining walls deteriorate because of excessive pressure buildup behind them, generally due to water accumulation. Conditions can often be improved by excavating a trench behind the retaining wall and filling it with coarse gravel. Drain holes through the wall will then be able to relieve the water pressure.

Retaining walls sometime suffer from tree root pressure or from general movement of topsoil down the slope. Normally, these conditions require rebuilding the retaining wall.

RAILINGS

It is recommended that railings be installed for any stairway over 3 steps and porches over 30" for safety reasons. Balusters for porches, balconies, and stairs should be close enough to assure children cannot squeeze through.



REMARKS

Valleys and Flashings that are covered with shingles and/or tar or any other material are considered not visible and are not part of the inspection.

Tar and Gravel Roofs are a type of covering on a pitched roof requires ongoing annual maintenance. We recommend that a roofing contractor evaluate this type of roof. Infra-red photography is best used to determine areas of potential leaks.

Flat roofs are very vulnerable to leaking. It is very important to maintain proper drainage to prevent the ponding of water. We recommend that a roofing contractor evaluate this type of roof.

ROOF TYPE	LIFE EXPECTANCY	SPECIAL REMARKS	
Asphalt Shingles	15-20 years	Used on nearly 80% of all residential roofs; requires little maintenance	
Asphalt Multi-Thickness Shingles*	20-30 years	Heavier and more durable than regular asphalt shingles	
Asphalt Interlocking Shingles*	15-25 years	Especially good in high-wind areas	
Asphalt Rolls	10 years	Used on low slope roofs	
Built-up Roofing	10-20 years	Used on low slope roofs; 2 to 3 times as costly as asphalt shingles	
Wood Shingles*	10-40 years ¹	Treat with preservative every 5 years to prevent decay	
Clay Tiles* Cement Tiles*	20 + years 20 + years	Durable, fireproof, but not watertight, requiring a good subsurface base	
Slate Shingles*	30-100 years ²	Extremely durable, but brittle and expensive	
Asbestos Cement Shingles*	30-75 years	Durable, but brittle and difficult to repair	
Metal Roofing	15-40 + years	Comes in sheets & shingles; should be well grounded for protection from lightning; certain metals must be painted	
Single Ply Membrane	15-25 years (mfgr's claim)	New material; not yet passed test of time	
Polyurethane with Elastomenic Coating	5-10 years ¹	Used on low slope roofs.	

^{*} Not recommended for use on low slope roof

Roof coverings should be visually checked in the spring and fall for any visible missing shingles, damaged coverings or other defects. Before re-roofing, the underside of the roof structure and roof sheathing should be inspected to determine that the roof structure can support the additional weight of the shingles.

Wood shakes and shingles will vary in aging, due to the quality of the material, installation, maintenance, and surrounding shade trees. Ventilation and drying of the wood material is critical in extending the life expectancy of the wood. Commercial preservatives are available on the market, which could be applied to wood to impede deterioration.

¹ Depending on local conditions and proper installation

² Depending on quality of slate

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 26 of 47



REMARKS

CHIMNEYS

Chimneys built of masonry will eventually need tuckpointing. A cracked chimney top that allows water and carbonic acid to get behind the surface brick/stone will accelerate the deterioration. Moisture will also deteriorate the clay flue liner. Periodic chimney cleaning will keep you apprised of the chimney's condition. The flashing around the chimney may need resealing and should be inspected every year or two. Fireplace chimneys should be inspected and evaluated by a chimney professional before using. Chimneys must be adequate height for proper drafting. Spark arrestors are recommended for a wood burning chimney, and chimney caps for fossil fuels.

Unlined Chimney should be re-evaluated by a chimney technician.

Have flue cleaned and re-evaluated. The flue lining is covered with soot or creosote and no representation can be made as to the condition.

NOT EVALUATED

The flue was not evaluated due to inaccessibility such as roof pitch, cap, cleanout not accessible, etc.

CRICKET FLASHING

Small, sloped structure made of metal and designed to drain moisture away from a chimney. Usually placed at the back of a chimney.

GUTTERS AND DOWNSPOUTS

This is an extremely important element in basement dampness control. Keep gutters clean and downspout extensions in place (4' or more). Paint the inside of galvanized gutters, which will extend the life. Shortly after a rain or thaw in winter, look for leaks at seams in the gutters. These can be recaulked before they cause damage to fascia or soffit boards. If no gutters exist, it is recommended that they be added.

SIDING

Wood siding should not come in contact with the ground. The moisture will cause rotting to take place and can attract carpenter ants. See page 34 for siding that have known problems, but are not always recognizable. EIFS This type of siding is a synthetic stucco and has experienced serious problems. It requires a certified EIFS inspector to determine condition.

Brick and stone veneer must be monitored for loose or missing mortar. Some brick and stone are susceptible to spalling. This can be caused when moisture is trapped and a freeze/thaw situation occurs. There are products on the market that can be used to seal out the moisture. This holds true for brick and stone chimneys also.

Metal siding will dent and scratch. Oxidation is a normal reaction in aluminum. There are good cleaners on the market and it is recommended that they be used occasionally. Metal siding can be painted.

DOORS AND WINDOWS

These can waste an enormous amount of energy. Maintain the caulking around the frames on the exterior. Check for drafts in the winter and improve the worst offenders first. Windows that have leaky storm windows will usually have a lot of sweating. Likewise, well-sealed storms that sweat indicate a leaky window. It is the tighter unit that will sweat (unless the home has excess humidity to begin with).

Wood that exhibits blistering or peeling paint should be examined for possible moisture sources: roof leaks, bad gutters, interior moisture from baths or laundry or from a poorly vented crawl space. Some paint problems have no logical explanation, but many are a symptom of an underlying problem. A freshly painted house may mask these symptoms, but after you have lived in the home for a year or two, look for localized paint blistering (peeling). It may be a clue.

New glazing will last longer if the raw wood is treated with boiled linseed oil prior to glazing. It prevents the wood from drawing the moisture out of the new glazing.

CAULKING

Many different types of caulk are available on the market today. Check with a paint or hardware store for the kind of application you need.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 27 of 47



REMARKS

EXTERIOR DOORS

The exposed side of exterior doors needs to be painted or properly stained and varnished to prevent discoloring and delamination. Weatherstripping is a must to prevent drafts.

ELECTRICAL

Extension cord wiring to an automatic door opener should be removed and an outlet should be installed by the opener.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 28 of 47



OVERHEAD DOOR OPENERS

We recommend that a separate electrical outlet be provided. Openers that do not have a **safety reverse** are considered a safety hazard. Small children and pets are especially vulnerable. We recommend the operating switches be set high enough so children cannot reach them. If a electric sensor is present, it should be tested occasionally to ensure it is working.

GARAGE SILL PLATES should be elevated or treated lumber should be used. If this is not the case, try to direct water away to prevent rotting.

A/C COMPRESSORS

They should not become overgrown with foliage. Clearance requirements vary, but 2' on all sides should be considered minimal with up to 6' of air discharge desirable. If a clothes dryer vent is within five to ten feet, either relocate the vent or do not run when the A/C is running. The lint will quickly reduce the efficiency of the A/C unit.

BURNERS

Any appliance such as a water heater, furnace, etc. should have the flame a minimum of 18" above the floor. Any open flame less than 18" from the floor is a potential safety hazard. The appliance should also be protected from vehicle damage.



PLASTER ON WOOD LATH

Plaster on wood lath is an old technique and is no longer in general use. Wood lath shrinks with time and the nails rust and loosen. As a result, the plaster may become fragile and caution is needed in working with this type of plastering system. Sagging ceilings are best repaired by laminating drywall over the existing plaster and screwing it to the ceiling joists.

PLASTER ON GYPSUM LATH (ROCK LATH)

Plaster on gypsum lath will sometimes show the seams of the 16" wide gypsum lath, but this does not indicate a structural fault. The scalloping appearance can be leveled with drywall joint compound and fiberglass mesh joint tape or drywall can be laminated over the existing plaster on the ceiling.

WOOD FLOORING

Always attempt to clean wood floors first before making the decision to refinish the floor. Wax removers and other mild stripping agents plus a good waxing and buffing will usually produce satisfactory results. Mild bleaching agents help remove deep stains. Sanding removes some of the wood in the floor and can usually be done safely only once or twice in the life of the floor.

NAIL POPS

Drywall nail pops are due to normal expansion and contraction of the wood members to which the drywall is nailed and are usually of no structural significance.

CARPETING

Where carpeting has been installed, the materials and condition of the floor underneath cannot be determined.

APPLIANCES

(If report indicated appliances were operated, the following applies) Dishwashers are tested to see if the motor operates and water sprays properly. Stoves are tested to see that burners are working and oven and broiler get hot. Timer and controls are not tested. Refrigerators are not tested.

No representation is made to continued life expectancy of any appliance.

ASBESTOS AND OTHER HAZARDS

Asbestos fibers in some form are present in many homes, but are often not visible and cannot be identified without testing.

If there is reason to suspect that asbestos may be present and if it is of particular concern, a sample of the material in question may be removed and analyzed in a laboratory. However, detecting or inspecting for the presence or absence of asbestos is not a part of our inspection.

Also excluded from this inspection and report are the possible presence of, or danger from, radon gas, lead-based paint, urea formaldehyde, toxic or flammable chemicals and all other similar or potentially harmful substances and environmental hazards.

WINDOWS

A representative number of windows are inspected.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 30 of 47



REMARKS

STALL SHOWER

The metal shower pan in a stall shower has a potential or probable life of 10-20 years depending on quality of the pan installed. Although a visible inspection is made to determine whether a shower pan is currently leaking, it cannot be stated with certainty that no defect is present or that one may not soon develop. Shower pan leaks often do not show except when the shower is in actual use.

CERAMIC TILE

Bathroom tile installed in a mortar bed is excellent. It is still necessary to keep the joint between the tile and the tub/shower caulked or sealed to prevent water spillage from leaking through and damaging the ceilings below. Ceramic tile is often installed in mastic. It is important to keep the tile caulked or water will seep behind the tile and cause deterioration in the wallboard. Special attention should be paid to the area around faucets and other tile penetrations.

EXHAUST FANS

Bathrooms with a shower should have exhaust fans when possible. This helps to remove excess moisture from the room, preventing damage to the ceiling and walls and wood finishes. The exhaust fan should not be vented into the attic. The proper way to vent the fan(s) is to the outside. Running the vent pipe horizontally and venting into a gable end or soffit is preferred. Running the vent pipe vertically through the roof may cause condensation to run down the vent pipe, rusting the fan and damaging the wallboard. Insulating the vent pipe in the attic will help to reduce this problem.

SLOW DRAINS on sinks, tubs, and showers are usually due to build up of hair and soap scum. Most sink popups can be easily removed for cleaning. Some tubs have a spring attached to the closing lever that acts as a catch for hair. It may require removing a couple of screws to disassemble. If you cannot mechanically remove the obstruction, be kind to your pipes. *Don't use a caustic cleaner*. There are several bacteria drain cleaners available. They are available at hardware stores in areas where septic tanks are used. These drain cleaners take a little longer to work, but are safe for you and your pipes.

SAFETY HAZARDS

Typical safety hazards found in bathrooms are open grounds or reverse polarity by water. Replacing these outlets with G.F.C.I.'s are recommended.

WHIRLPOOL TUBS

This relates to interior tubs hooked up to interior plumbing. Where possible, the motor will be operated to see that the jets are working. Hot tubs and spas are not inspected.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 31 of 47



DOOR STOPS

All swinging doors should be checked for door stops. Broken or missing door stops can result in door knobs breaking through drywall or plaster.

CLOSET GUIDES

Sliding closet doors should be checked to see that closet guides are in place. Missing or broken closet guides can cause scratches and damage to doors.

COLD AIR RETURNS

Bedrooms that do not have cold air returns in them should have a 3/4" gap under the doors to allow cold air to be drawn into the hall return.

AN INSPECTION VERSUS A WARRANTY

A home inspection is just what the name indicates, an inspection of a home...usually a home that is being purchased. The purpose of the inspection is to determine the condition of the various systems and structures of the home. While an inspection performed by a competent inspection company will determine the condition of the major components of the home, no inspection will pick up every minute latent defect. The inspector's ability to find all defects is limited by access to various parts of the property, lack of information about the property and many other factors. A good inspector will do his or her level best to determine the condition of the home and to report it accurately. The report that is issued is an opinion as to the condition of the home. This opinion is arrived at by the best technical methods available to the home inspection industry. It is still only an opinion.

A warranty is a policy sold to the buyer that warrants that specific items in the home are in sound condition and will remain in sound condition for a specified period of time. Typically, the warranty company never inspects the home. The warranty company uses actuarial tables to determine the expected life of the warranted items and charges the customer a fee for the warranty that will hopefully cover any projected loss and make a profit for the warranty seller. It is essentially an insurance policy.

The service that we have provided you is an inspection. We make no warranty of this property. If you desire warranty coverage, please see your real estate agent for details about any warranty plan to which their firm may have access.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 32 of 47



REMARKS

WINDOW FRAMES AND SILLS

Window frames and sills are often found to have surface deterioration due to condensation that has run off the window and damaged the varnish. Usually this can be repaired with a solvent style refinisher and fine steel wool. This is sometimes a sign of excess humidity in the house.

See comments regarding caulking doors and windows.

FIREPLACES

It is important that a fireplace be cleaned on a routine basis to prevent the buildup of creosote in the flue, which can cause a chimney fire.

Masonry fireplace chimneys are normally required to have a terra cotta flue liner or 8 inches of masonry surrounding each flue in order to be considered safe and to conform with most building codes.

During visual inspections, it is not uncommon to be unable to detect the absence of a flue liner either because of stoppage at the firebox, a defective damper or lack of access from the roof.

WOODBURNERS

Once installed, it can be difficult to determine proper clearances for woodburning stoves. Manufacturer specifications, which are not usually available to the inspector, determine the proper installation. We recommend you ask the owner for paperwork, verifying that it was installed by a professional contractor.

VENTILATION

Ventilation is recommended at the rate of one square foot of vent area to 300 square feet of attic floor space, this being divided between soffit and rooftop. Power vents should ideally have both a humidistat and a thermostat, since ventilation is needed to remove winter moisture as well as summer heat. Evidence of condensation such as blackened roof sheathing, frost on nail heads, etc. is an indication that ventilation may have been or is blocked or inadequate.

INSULATION

The recommended insulation in the attic area is R-38, approximately 12". If insulation is added, it is important that the ventilation is proper.

SMOKE DETECTORS

Smoke detectors should be tested monthly. At least one detector should be on each level. CO detectors are not required by most states, but for safety reasons, are highly recommended.

VAPOR BARRIERS

The vapor barrier should be on the warm side of the surface. Most older homes were built without vapor barriers. If the vapor barrier is towards the cold side of the surface, it should be sliced or removed. Most vapor barriers in the attic are covered by insulation and therefore, not visible.

SAFETY GLAZING

Safety glazing requirements vary depending on the age of the home. Every attempt is made to identify areas where the lack of safety glazing presents an immediate safety hazard, such as a shower door. In some older homes it is difficult to determine if safety glazing is present, since the glass is not marked. Therefore, no representation is made that safety glazing exists in all appropriate areas.

INSULATED GLASS

Broken seal in thermopane/insulated windows are not always visible nor detectible due to humidity and temperature changes during the day. Other factors such as window covering, dirty windows, and lack of accessibility, personal property placed in front of the windows all effect the view of the windows at the time of the inspection.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 33 of 47



REMARKS

BASEMENT

Any basement that has cracks or leaks is technically considered to have failed. Most block basements have step cracks in various areas. If little or no movement has occurred and the step cracks are uniform, this is considered acceptable. Horizontal cracks in the third or fourth block down indicate the block has moved due to outside pressure. They can be attributed to many factors such as improper grading, improperly functioning gutter and downspout system, etc. Normally if little or no movement has taken place and proper grading and downspouts exist, this is considered acceptable. If the wall containing the stress crack(s) has moved considerably, this will require some method of reinforcement. Basements that have been freshly painted or tuckpointed should be monitored for movement. This will be indicated by cracks reopening. If cracks reappear, reinforcement may be necessary. Reinforcing a basement wall can become expensive.

FOUNDATION (COVERED WALLS)

Although an effort has been made to note any major inflections or weaknesses, it is difficult at best to detect these areas when walls are finished off, or basement storage makes areas inaccessible. **No representation is made as to the condition of these walls.**

MONITOR indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be filled with mortar and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.

HAVE EVALUATED We recommend that the walls be re-evaluated by a structural engineer or basement repair company and estimates be obtained if work is required.

VAPOR BARRIER

Floors that are dirt or gravel should be covered with a vapor barrier.

MOISTURE PRESENT

Basement dampness is frequently noted in houses and in most cases the stains, moisture or efflorescence present is a symptom denoting that a problem exists outside the home. Usual causes are improper downspout extensions or leaking gutters and/or low or improper grade (including concrete surfaces) at the perimeter of the house. A proper slope away from the house is one inch per foot for four to six feet.

Expensive solutions to basement dampness are frequently offered. It is possible to spend thousands of dollars on solutions such as pumping out water that has already entered or pumping of chemical preparations into the ground around the house, when all that may be necessary are a few common sense solutions at the exterior perimeter. However, this is not intended to be an exhaustive list of causes and solutions to the presence of moisture. **No representation is made to future moisture that may appear.**

PALMER VALVE

Many older homes have a valve in the floor drain. This drain needs to remain operational.

DRAIN TILE

We offer no opinion about the existence or condition of the drain tile, as it cannot be visibly inspected.

BASEMENT ELECTRICAL OUTLETS

We recommend that you have an outlet within 6' of each appliance. The appliance you plan to install may be different than what exists, therefore the inspection includes testing a representative number of receptacles that exist. It is also recommended to have ground fault circuit interrupts for any outlet in the unfinished part of the basement and crawl spaces.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 34 of 47



REMARKS

CRAWL SPACES

Crawl spaces are shallow spaces between the first level floor joist and the ground. Access to this area may be from the inside, outside or not accessible at all. Ductwork, plumbing, and electrical may be installed in the space in which access may be necessary. The floor of the crawl space may be covered with concrete, gravel, or may be the original soil. A vapor barrier may be a sheet of plastic or tar paper and installed over or under this material. The vapor barrier will deter the moisture from the earth from escaping into the crawl space and causing a musty smell. Ventilation is also important to control excess moisture buildup. Vents may be located on the outside of the house and are normally kept open in the summer and closed for the winter (where freezing may occur).

The basement/crawl space diagram indicates areas that are covered and not part of a visual inspection. Every attempt is made to determine if paneling is warped, moisture stains are bleeding through, etc. Storage that blocks the visibility of a wall is not removed to examine that area. Therefore, it is important that on your walk-through before closing, you closely examine these areas.

Closed crawl spaces that have vents to the outside should have insulation under the floor above the crawl space.

HAVE EVALUATED

We recommend that the walls be re-evaluated by a structural engineer or basement repair company and estimates be obtained if work is required.

MONITOR

Indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be filled with mortar and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 35 of 47



WELLS

Examination of wells is not included in this visual inspection. It is recommended that you have well water checked for purity by the local health authorities and, if possible, a check on the flow of the well in periods of drought. A well pit should have a locked cover on it to prevent anyone from falling into the pit.

SEPTIC SYSTEMS

The check of septic systems is not included in our visual inspection. You should have the local health authorities or other qualified experts check the condition of the septic system.

In order for the septic system to be checked, the house must have been occupied within the last 30 days.

WATER PIPES

Galvanized water pipes rust from the inside out and may have to be replaced within 20 to 30 years. This is usually done in two stages: horizontal piping in the basement first, and vertical pipes throughout the house later as needed. Copper pipes usually have more life expectancy and may last as long as 60 years before needing to be replaced.

HOSE BIBS

During the winter months it is necessary to make sure the outside faucets are winterized. This can be done by means of a valve located in the basement. Leave the outside faucets open to allow any water standing in the pipes to drain, preventing them from freezing. Hose bibs cannot be tested when winterized.

WATER HEATER

The life expectancy of a water heater is 5-10 years. Water heaters generally need not be replaced unless they leak. It is a good maintenance practice to drain 5-10 gallons from the heater several times a year. Missing relief valves or improper extension present a safety hazard.

WATER SOFTENERS

During a visual inspection it is not possible to determine if water is being properly softened.

PLUMBING

The temperature/pressure valve should be tested several times a year by lifting the valve's handle. Caution: very hot water will be discharged. If no water comes out, the valve is defective and must be replaced.

SHUT-OFF VALVES

Most shut-off valves have not been operated for long periods of time. We recommend operating each shut-off valve to: toilet bowl, water heater, under sinks, main shut-off, hose faucets, and all others. We recommend you have a plumber do this, as some of the valves may need to be repacked or replaced. Once the valves are in proper operating order, we recommend opening and closing these valves several times a year.

POLYBUTYLENE PIPING

This type of piping has a history of problems and should be examined by a licensed plumber and repaired or replaced as necessary.

MECHANICAL DEVICES MAY OPERATE AT ONE MOMENT AND LATER MALFUNCTION; THEREFORE, LIABILITY IS SPECIFICALLY LIMITED TO THOSE SITUATIONS WHERE IT CAN BE CONCLUSIVELY SHOWN THAT THE MECHANICAL DEVICE INSPECTED WAS INOPERABLE OR IN THE IMMEDIATE NEED OF REPAIR OR NOT PERFORMING THE FUNCTION FOR WHICH IS IT WAS INTENDED AT THE TIME OF INSPECTION.

CSST

Corrugated Stainless Steel Tubing is an alternative to traditional black iron gas piping. It is a continuous, flexible, stainless steel pipe with an exterior PVC covering.



REMARKS

HEATING AND AIR CONDITIONING units have limited lives. Normal lives are:

Gas-fired hot air units that are close to or beyond their normal lives have the potential of becoming a source of carbon monoxide in the home. You may want to have such a unit checked every year or so to assure yourself that it is still intact. Of course a unit of such an age is a good candidate for replacement with one of the new, high efficiency furnaces. The fuel savings alone can be very attractive.

Boilers and their systems may require annual attention. If you are not familiar with your system, have a heating contractor come out in the fall to show you how to do the necessary thing **Caution: do not add water to a hot boiler!**

Forced air systems should have filters changed every 30 to 60 days of the heating and cooling season. This is especially true if you have central air conditioning. A dirty air system can lead to premature failure of your compressor - a \$1,500 machine.

Oil-fired furnaces and boilers should be serviced by a professional each year. Most experts agree you will pay for the service cost in fuel saved by having a properly tuned burner.

Read the instructions for maintaining the humidifier on your furnace. A malfunctioning humidifier can rust out a furnace rather quickly. It is recommended that the humidifier be serviced at the same time as the furnace, and be cleaned regularly. **During a visual inspection it is not possible to determine if the humidifier is working.**

Have HVAC technician examine - A condition was found that suggests a heating contractor should do a further analysis. We suggest doing this before closing.

Heat exchangers cannot be examined nor their condition determined without being disassembled. Since this is not possible during a visual, non-technically exhaustive inspection, you may want to obtain a service contract on the unit or contact a furnace technician regarding a more thorough examination.

Testing pilot safety switch requires blowing out the pilot light. Checking safety limit controls requires disconnecting blower motor or using other means beyond the scope of this inspection. If the furnace has not been serviced in last 12 months you may want to have a furnace technician examine.

CO Test This is not part of a non-technical inspection. If a test was performed, the type of tester is indicated on the Heating System page.


Combustible Gas Detector If a gas detector was used during the inspection of the furnace and evidence of possible combustible gases was noted, we caution you that our test instrument is sensitive to many gases and not a foolproof test. None-the-less, this presents the possibility that a hazard exists and could indicate that the heat exchanger is, or will soon be, defective.



REMARKS

Every effort has been made to evaluate the size of the service. Three wires going into the home indicate 240 volts. The total amperage can be difficult to determine. We highly recommend that ground fault circuit interrupters (G.F.C.I.) be connected to all outlets around water. This device automatically shuts the circuit off when it senses a current leak to ground. This device can be purchased in most hardware stores. G.F.C.I.'s are recommended by all outlets located near water, outside outlets, or garage outlets. Pool outlets should also be protected with a G.F.C.I.

See diagram below:



If you do have G.F.C.I.'s, it is recommended that you test (and reset) them monthly. When you push the test button, the reset button should pop out, shutting off the circuit. If it doesn't, the breaker is not working properly. If you don't test them once a month, the breakers have a tendency to stick and may not protect you when needed.

Knob and tube wiring found in older homes should be checked by an electrician to insure that the wire cover is in good condition. Under no circumstances should this wire be covered with insulation. Recess light fixtures should have a baffle around them so that they are not covered with insulation. The newer recessed fixtures will shut off if they overheat. (no representation is made as to proper recess lighting fixtures).

Federal Pacific Stab-Lok® Electrical panels may be unsafe. See www.google.com (Federal Pacific)

Aluminum wiring in general lighting circuits has a history of over heating, with the potential of a fire. If this type of wiring exists, a licensed electrical contractor should examine the whole system.

ARC FAULTS

In some areas arc faults are required in new homes, starting in 2002 and these control outlets in the bedrooms.

REVERSE POLARITY

A common problem that surfaces in many homes is reverse polarity. This is a potentially hazardous situation in which the hot and neutral wires of a circuit are reversed at the outlet, thereby allowing the appliance to incorrectly be connected. This is an inexpensive item to correct.

Each receptacle has a brass and silver screw. The black wire should be wired to the brass screw and the white wire should go to the silver screw. When these wires are switched, this is called "reverse polarity." Turning off the power and switching these wires will correct the problem.

Main service wiring for housing is typically 240 volts. The minimum capacity for newer homes is 100 amps though many older homes still have 60 amp service. Larger homes or all electric homes will likely have a 200 amp service.

Main service wiring may be protected by one or more circuit breakers or fuses. While most areas allow up to six main turnoffs, expanding from these panels is generally not allowed.

COOLING

Testing A/C System and Heat Pump- The circuit breakers to A/C should be on for a minimum of 24 hours and the outside temperature at least 60 degrees for the past 24 hours or an A/C system cannot be operated without possible damage to the compressor. Check the instructions in your A/C manual or on the outside compressor before starting up in the summer. Heat pump can only be tested in the mode it's running in. Outside temperature should be at least 65° for the past 24 hours to run in cooling mode.

Temperature differential, between 14°-22°, is usually acceptable. If out of this range, have an HVAC contractor examine it. It is not always feasible to do a differential test due to high humidity, low outside temperature, etc.

COSTS OF REMODELING OR REPAIR

The prices quoted below include a range of prices based on a typical metropolitan area. Individual prices from contractors can vary substantially from these ranges. We advise that several bids be obtained on any work exceeding \$500 dollars. **DO NOT RELY ON THESE PRICES... GET FURTHER ESTIMATES.**

ITEM	UNIT	ESTIMATED PRICE
Masonry fireplace	Each	\$4,000 - \$8,000
Install prefab fireplace	Each	2,000 - 4,000
Insulate attic	Square foot	.75 - 1.25
Install attic ventilating fan	Each	200 - 300
Install new drywall over plaster	Square foot	1.75 - 2.75
Install new warm air furnace	Each	1,800 - 3,500
Replace central air conditioning/heat pump	Per ton	1,000 - 1,500
Install humidifier	Each	300 - 500
Install electrostatic air cleaner	Each	800 - 1,500
Increase electrical service to 200 amps	Each	1,000 - 1,500
Run separate elec. line for dryer	Each	125 - 200
Run separate elec. line for A/C	Each	135 - 200
Install hardwired smoke detector	Each	100 - 180
Install new disposal	Each	150 - 250
Install new dishwasher	Each	500 - 1,000
Install new hot water boiler	Each	2,000 - 4,000
Install new 30-50 gallon water heater	Each	350 - 650
Install new 75 gallon water heater	Each	750 - 1,000
Dig and install new well	Each	get estimate
Install new septic system	Each	get estimate
Re-grade around exterior	Each	get estimate
Install new sump pump	Each	150 - 300
Build new redwood or pressure-	Square foot	15 - 30
treated deck		
Install storm windows	Each	60 - 150
Install wood replacement windows	Each	400 - 800
Install aluminum or vinyl	Each	150 - 400
replacement window		
Install new gutters and downspouts	Lineal foot	4.00 - 8.00
Install asphalt shingle o/existing	Square foot	1.20 - 1.70
Tear off existing roof and install	Square foot	2.50 - 4.00
new asphalt shingle roof		
Install 1-ply membrane rubberized roof	Square foot	get estimate
Install new 4-ply built-up tar & gravel	Square foot	get estimate
Remove asbestos from pipes in basement	Lineal foot	get estimate
Concrete drive or patio	Square foot	4.50 - 9.00
Plus removal of old	Square foot	1.50 - 3.00
Clean chimney flue	Each	100 - 200
Add flue liner for gas fuel	Each	900 - 1,200
Add flue liner for oil or wood	Each	2,800 - 3,500

Deferred Costs - It is impossible to determine how long these items will last before needing replacement. The report addresses most of these items from a "condition" standpoint.

PREVENTIVE MAINTENANCE TIPS

- I. FOUNDATION & MASONRY: Basements, Exterior Walls: To prevent seepage and condensation problems.
 - a. Check basement for dampness & leakage after wet weather.
 - b. Check chimneys, deteriorated chimney caps, loose and missing mortar.
 - c. Maintain grading sloped away from foundation walls.
- **II. ROOFS & GUTTERS:** To prevent roof leaks, condensation, seepage and decay problems.
 - a. Check for damaged, loose or missing shingles, blisters.
 - b. Clean gutters, leaders, strainers, window wells, drains. Be sure downspouts direct water away from foundation. Cut back tree limbs.
 - c. Check flashings around roof stacks, vents, skylights, chimneys, as sources of leakage. Check vents, louvers and chimneys for birds nests, squirrels, insects.
 - d. Check fascias and soffits for paint flaking, leakage & decay.
- **III. EXTERIOR WALLS:** To prevent paint failure, decay and moisture penetration problems.
 - a. Check painted surface for paint flaking or paint failure. Cut back shrubs.
 - b. Check exterior masonry walls for cracks, looseness, missing or broken mortar.
- **IV. DOORS AND WINDOWS:** To prevent air and weather penetration problems.
 - a. Check caulking for decay around doors, windows, corner boards, joints. Recaulk and weatherstrip as needed. Check glazing, putty around windows.
- V. **ELECTRICAL:** For safe electrical performance, mark & label each circuit.
 - a. Trip circuit breakers every six months and ground fault circuit interrupters (G.F.C.I.) monthly.
 - b. Check condition of lamp cords, extension cords & plugs. Replace at first sign of wear & damage.
 - c. Check exposed wiring & cable for wear or damage.
 - d. If you experience slight tingling shock from handling or touching any appliance, disconnect the appliance
 - & have it repaired. If lights flicker or dim, or if appliances go on and off unnecessarily, call a licensed electrician.
- **VI. PLUMBING:** For preventive maintenance.
 - a. Drain exterior water lines, hose bibs, sprinklers, pool equipment in the fall.
 - b. Draw off sediment in water heaters monthly or per manufacturer's instructions.
 - c. Have septic tank cleaned every 2 years.
- VII. **HEATING & COOLING:** For comfort, efficiency, energy conservation and safety.
 - a. Change or clean furnace filters, air condition filters, electronic filters as needed.
 - b. Clean and service humidifier. Check periodically and annually.
 - c. Have oil burning equipment serviced annually.
- **VIII. INTERIOR:** General house maintenance.
 - a. Check bathroom tile joints, tub grouting & caulking. Be sure all tile joints in bathrooms are kept well sealed with tile grout to prevent damage to walls, floors & ceilings below.
 - b. Close crawl vents in winter and open in summer.
 - c. Check underside of roof for water stains, leaks, dampness & condensation, particularly in attics and around chimneys.

IX. Know the location of:

- Main water shutoff valve.
- Main electrical disconnect or breaker.
- Main emergency shutoff switch for the heating system.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 40 of 47

AMERICAN SOCIETY OF HOME INSPECTORS®

Standards of Practice

- 1. Introduction
- 2. Purpose & Scope
- 3. Structural System
- 4. Exterior
- 5. Roofing System
- 6. Plumbing System
- 7. Electrical System
- 8. Heating System
- 9. Air Conditioning System
- 10. Interior
- 11. Insulation & Ventilation
- 12. Fireplaces & Solid Fuel Burning Appliances
- 13. General Limitations & Exclusions Glossary

Effective 1 January 2000 © 2000 American Society of Home Inspectors®

1. INTRODUCTION

1.1 The American Society of Home Inspectors®, Inc. (ASHI®) is a not-for-profit professional society established in 1976. Membership in ASHI is voluntary and its members include private, fee-paid home *inspectors*. ASHI®'s objectives include promotion of excellence within the profession and continual improvement of its members' inspection services to the public.

2. PURPOSE AND SCOPE

2.1 The purpose of these Standards of Practice is to establish a minimum and uniform standard for private, fee-paid home *inspectors* who are members of the American Society of Home Inspectors. *Home inspections* performed to these Standards of Practice are intended to provide the client with information regarding the condition of the *systems* and *components* of the home as *inspected* at the time of the *Home Inspection*.

2.2 The inspector shall:

- A. inspect:
 - readily accessible systems and components of homes listed in these Standards of Practice.
 - 2. installed systems and components of homes listed in these Standards of Practice.
- B. report:
 - 1. on those *systems* and *components inspected* which, in the professional opinion of the *inspector*, are *significantly deficient* or are near the end of their service lives.
 - 2. A reason why, if not self-evident, the system or component is *significantly deficient* or near the end of its service life.
 - 3. the *inspector's* recommendations to correct or monitor the *reported* deficiency.
 - 4. on any *systems* and *components* designated for inspection in these Standards of Practice which were present at the time of the *Home Inspection* but were not *inspected* and the reason they were not *inspected*.

2.3 These Standards of Practice are not intended to limit inspectors from:

A. including other inspection services, *systems* or *components* in addition to those required by these Standards of Practice.

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 41 of 47

- B. specifying repairs, provided the *inspector* is appropriately qualified and willing to do so.
- C. excluding *systems* and *components* from the inspection if requested by the client.

3. STRUCTURAL SYSTEM

3.1 The *inspector* shall:

A. inspect:

- 1. the *structural components* including foundation and framing.
- 2. by probing a *representative number* of *structural components* where deterioration is suspected or where clear indications of possible deterioration exist. Probing is NOT required when probing would damage any finished surface or where no deterioration is visible.

B. describe:

- 1. the foundation and *report* the methods used to *inspect* the *under-floor crawl space*.
- 2. the floor structure.
- 3. the wall structure.
- 4. the ceiling structure.
- 5. the roof structure and *report* the methods used to *inspect* the attic.

3.2 The *inspector* is NOT required to:

- A. provide any engineering service or architectural service.
- B. offer an opinion as to the adequacy of any structural system or component.

4. EXTERIOR

4.1 The inspector shall:

A. inspect:

- 1. the exterior wall covering, flashing and trim.
- 2. all exterior doors.
- 3. attached decks, balconies, stoops, steps, porches, and their associated railings.
- 4. the eaves, soffits, and fascias where accessible from the ground level.
- 5. the vegetation, grading, surface drainage, and retaining walls on the property when any of these are likely to adversely affect the building.
- 6. walkways, patios, and driveways leading to dwelling entrances.
- B. describe the exterior wall covering.

4.2 The inspector is NOT required to:

A. inspect:

- 1. screening, shutters, awnings, and similar seasonal accessories.
- fences.
- 3. geological, geotechnical, or hydrological conditions.
- 4. recreational facilities.
- 5. outbuildings.
- 6. seawalls, break-walls, and docks.
- 7. erosion control and earth stabilization measures.

5. ROOF SYSTEM

5.1 The *inspector* shall:

A. inspect:

- 1. the roof covering.
- 2. the roof drainage systems.
- 3. the flashings.
- 4. the skylights, chimneys, and roof penetrations.
- B. describe the roof covering and report the methods used to inspect the roof.

5.2 The *inspector* is NOT required to:

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 42 of 47

A. inspect:

- 1. antennae.
- 2. interiors of flues or chimneys which are not readily accessible.
- 3. other installed accessories.

6. PLUMBING SYSTEM

6.1 The inspector shall:

A. inspect:

- 1. the interior water supply and distribution systems including all fixtures and faucets.
- 2. the drain, waste and vent systems including all fixtures.
- 3. the water heating equipment
- 4. the vent systems, flues, and chimneys.
- 5. the fuel storage and fuel distribution *systems*.
- 6. the drainage sumps, sump pumps, and related piping.

B. describe:

- 1. the water supply, drain, waste, and vent piping materials.
- 2. the water heating equipment including the energy source.
- 3. the location of main water and main fuel shut-off valves.

6.2 The inspector is NOT required to:

A. inspect:

- 1. the clothes washing machine connections.
- 2. the interiors of flues or chimneys which are not *readily accessible*.
- 3. wells, well pumps, or water storage related equipment.
- 4. water conditioning systems.
- 5. solar water heating systems.
- 6. fire and lawn sprinkler systems.
- 7. private waste disposal systems.

B. determine:

- 1. whether water supply and waste disposal *systems* are public or private.
- 2. the quantity or quality of the water supply.
- 3. operate safety valves or shut off valves.

7. ELECTRICAL SYSTEM

7.1 The inspector shall:

A. inspect:

- 1. the service drop.
- 2. the service entrance conductors, cables, and raceways.
- 3. the service equipment and main disconnects.
- 4. the service grounding.
- 5. the interior *components* of service panels and sub panels.
- 6. the conductors.
- 7. the overcurrent protection devices.
- 8. a representative number of installed lighting fixtures, switches, and receptacles.
- 9. the ground fault circuit interrupters.

B. describe:

- 1. the amperage and voltage rating of the service
- 2. the location of main disconnect(s) and sub panels
- 3. the wiring methods

C. report:

- 1. on the presence of solid conductor aluminum branch circuit wiring
- 2. on the absence of smoke detectors

7.2 The *inspector* is NOT required to:

A. inspect:

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 43 of 47

- 1. the remote control devices unless the device is the only control device.
- 2. the alarm systems and components.
- 3. the low voltage wiring, systems and components.
- 4. the ancillary wiring, *systems* and *components* not a part of the primary electrical power distribution *system*.
- B. measure amperage, voltage, or impedance.

8. HEATING SYSTEM

8.1 The inspector shall:

A. inspect:

- 1. the *installed* heating equipment.
- 2. the vent systems, flues, and chimneys.

B. describe

- 1. the energy source.
- 2. the heating method by its distinguishing characteristics.

8.2 The inspector is NOT required to:

A. inspect:

- 1. the interiors of flues or chimneys which are not *readily accessible*.
- 2. the heat exchanger.
- 3. the humidifier or dehumidifier.
- 4. the electronic air filter.
- 5. the solar space heating system.
- B. determine heat supply adequacy or distribution balance.

9. AIR CONDITIONING SYSTEMS

9.1 The inspector shall:

- A. inspect the installed central and through-wall cooling equipment.
- B. describe:
 - 1. the energy source.
 - 2. the cooling method by its distinguishing characteristics.

9.2 The *inspector* is NOT required to:

- A. *inspect* electronic air filters.
- B. determine cooling supply adequacy or distribution balance.

10. INTERIOR

10.1 The *inspector* shall:

A. inspect:

- 1. the walls, ceilings, and floors.
- 2. the steps, stairways, and railings.
- 3. the countertops and a *representative number* of *installed* cabinets.
- 4. a representative number of doors and windows.
- 5. garage doors and garage door operators.

10.2 The *inspector* is NOT required to:

A. inspect:

- 1. the paint, wallpaper, and other finish treatments.
- 2. the carpeting.
- 3. the window treatments.
- 4. the central vacuum systems.
- 5. the household appliances.
- 6. recreational facilities.

11. INSULATION & VENTILATION

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 44 of 47

11.1 The inspector shall:

- A. inspect:
 - 1. the insulation and vapor retarders in unfinished spaces.
 - 2. the ventilation of attics and foundation areas.
 - 3. the mechanical ventilation systems.
- B. describe:
 - 1. the insulation and vapor retarders in unfinished spaces.
 - 2. the absence of insulation in unfinished spaces at conditioned surfaces.

11.2 The *inspector* is NOT required to:

- A. disturb insulation or vapor retarders.
- B. determine indoor air quality.

12. FIREPLACES AND SOLID FUEL BURNING APPLIANCES

12.1 The *inspector* shall:

- A. inspect:
 - 1. the system components.
 - 2. the vent systems, flues, and chimneys.
- B. describe:
 - 1. the fireplaces and solid fuel burning appliances.
 - 2. the chimneys.

12.2 The inspector is NOT required to:

- A. inspect:
 - 1. the interiors of flues or chimneys.
 - 2. the firescreens and doors.
 - 3. the seals and gaskets.
 - 4. the automatic fuel feed devices.
 - 5. the mantles and fireplace surrounds.
 - 6. the combustion make-up air devices.
 - 7. the heat distribution assists whether gravity controlled or fan assisted.
- B. ignite or extinguish fires.
- C. determine draft characteristics.
- D. move fireplace inserts or stoves or firebox contents.

13. GENERAL LIMITATIONS AND EXCLUSIONS

13.1 General limitations:

- A. Inspections performed in accordance with these Standards of Practice
 - 1. are not technically exhaustive.
 - 2. will not identify concealed conditions or latent defects
- B. These Standards of Practice are applicable to buildings with four or fewer dwelling units and their garages or carports.

13.2 General exclusions:

- A. The *inspector* is not required to perform any action or make any determination unless specifically stated in these Standards of Practice, except as may be required by lawful authority. B. *Inspectors* are NOT required to determine:
 - 1. the condition of systems or components which are not readily accessible.
 - 2. the remaining life of any system or component.
 - 3. the strength, adequacy, effectiveness, or efficiency of any system or component.
 - 4. the causes of any condition or deficiency.
 - 5. the methods, materials, or costs of corrections.
 - 6. future conditions including, but not limited to, failure of systems and components.
 - 7. the suitability of the property for any specialized use.
 - 8. compliance with regulatory requirements (codes, regulations, laws, ordinances, etc.).

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 45 of 47

- 9. the market value of the property or its marketability.
- 10. the advisability of the purchase of the property.
- 11. the presence of potentially hazardous plants or animals including, but not limited to wood destroying organisms or diseases harmful to humans.
- 12. the presence of any environmental hazards including, but not limited to toxins, carcinogens, noise, and contaminants in soil, water, and air.
- 13. the effectiveness of any system *installed* or methods utilized to control or remove suspected hazardous substances.
- 14. the operating costs of systems or components.
- 15. the acoustical properties of any system or component.
- C. Inspectors are NOT required to offer:
 - 1. or perform any act or service contrary to law.
 - 2. or perform engineering services.
 - 3. or perform work in any trade or any professional service other than *home inspection*.
 - 4. warranties or guarantees of any kind.
- D. Inspectors are NOT required to operate:
 - 1. any system or component which is shut down or otherwise inoperable.
 - 2. any system or component which does not respond to normal operating controls.
 - 3. shut-off valves.
- E. Inspectors are NOT required to enter:
 - 1. any area which will, in the opinion of the *inspector*, likely be dangerous to the *inspector* or other persons or damage the property or its *systems* or *components*.
 - 2. the *under-floor crawl spaces* or attics which do not conform to recognized standards for clearance.
- F. *Inspectors* are NOT required to *inspect*:
 - 1. underground items including, but not limited to underground storage tanks or other underground indications of their presence, whether abandoned or active.
 - 2. systems or components which are not installed.
 - 3. decorative items.
 - 4. *systems* or *components* located in areas which are not entered in accordance with these Standards of Practice.
 - 5. detached structures other than garages and carports.
 - 6. common elements or common areas in multi-unit housing, such as condominium properties or cooperative housing.
- G. *Inspectors* are NOT required to:
 - 1. perform any procedure or operation which will, in the opinion of the *inspector*, likely be dangerous to the *inspector* or other persons or damage the property or its *systems* or *components*.
 - 2. move suspended ceiling tiles, personal property, furniture, equipment, plants, soil, snow, ice, or debris.
 - dismantle any system or component, except as explicitly required by these Standards of Practice.

GLOSSARY OF ITALICIZED WORDS

Alarm Systems

Warning devices, *installed* or free-standing, including but not limited to; carbon monoxide detectors, flue gas and other spillage detectors, security equipment, ejector pumps and smoke alarms

Architectural Service

Any practice involving the art and science of building design for construction of any structure or grouping of structures and the use of space within and surrounding the structures or the design for construction, including but not specifically limited to, schematic design, design development, preparation of construction contract documents, and administration of the construction contract

Automatic Safety Controls

Devices designed and installed to protect systems and components from unsafe conditions

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 46 of 47

Component

A part of a system

Decorative

Ornamental; not required for the proper operation of the essential systems and components of a home

Describe

To report a *system* or *component* by its type or other observed, significant characteristics to distinguish it from other *systems* or *components*

Dismantle

To take apart or remove any *component*, device or piece of equipment that would not be taken apart or removed by a homeowner in the course of normal and routine home owner maintenance

Engineering Service

Any professional service or creative work requiring engineering education, training, and experience and the application of special knowledge of the mathematical, physical and engineering sciences to such professional service or creative work as consultation, investigation, *evaluation*, planning, design and supervision of construction for the purpose of assuring compliance with the specifications and design, in conjunction with structures, buildings, machines, equipment, works or processes

Further Evaluation

Examination and analysis by a qualified professional, tradesman or service technician beyond that provided by the *home inspection*

Home Inspection

The process by which an inspector visually examines the *readily accessible systems* and *components* of a home and which describes those *systems* and *components* in accordance with these Standards of Practice

Household Appliances

Kitchen, laundry, and similar appliances, whether installed or free-standing

Inspect

To examine readily accessible *systems* and *components* of a building in accordance with these Standards of Practice, using *normal operating controls* and opening *readily openable access panels*

Inspector

A person hired to examine any system or component of a building in accordance with these Standards of Practice

Installed

Attached such that removal requires tools

Normal Operating Controls

Devices such as thermostats, switches or valves intended to be operated by the homeowner

Readily Accessible

Available for visual inspection without requiring moving of personal property, *dismantling*, destructive measures, or any action which will likely involve risk to persons or property

Readily Openable Access Panel

A panel provided for homeowner inspection and maintenance that is within normal reach, can be removed by one person, and is not sealed in place

Recreational Facilities

Spas, saunas, steam baths, swimming pools, exercise, entertainment, athletic, playground or other similar equipment and associated accessories

1793 North Applebury Place, Fayetteville, Arkansas 72701 Page 47 of 47

Report

To communicate in writing

Representative Number

One *component* per room for multiple similar interior *components* such as windows and electric outlets; one *component* on each side of the building for multiple similar exterior *components*

Roof Drainage Systems

Components used to carry water off a roof and away from a building

Significantly Deficient

Unsafe or not functioning

Shut Down

A state in which a system or component cannot be operated by normal operating controls

Solid Fuel Burning Appliances

A hearth and fire chamber or similar prepared place in which a fire may be built and which is built in conjunction with a chimney; or a listed assembly of a fire chamber, its chimney and related factory-made parts designed for unit assembly without requiring field construction

Structural Component

A *component* which supports non-variable forces or weights (dead loads) and variable forces or weights (live loads)

System

A combination of interacting or interdependent components, assembled to carry out one or more functions

Technically Exhaustive

An investigation that involves *dismantling*, the extensive use of advanced techniques, measurements, instruments, testing, calculations, or other means

Under-Floor Crawl Space

The area within the confines of the foundation and between the ground and the underside of the floor

Unsafe

A condition in a readily accessible, *installed component* or *system* which is judged to be a significant risk of personal injury during normal, day-to-day use. The risk may be due to damage, deterioration, improper installation or a change in accepted residential construction standards

Wiring Methods

Identification of electrical conductors or wires by their general type, such as "non-metallic sheathed cable" ("Romex"), "armored cable" ("bx") or "knob and tube," etc.